1/9/2011	Flight Phase	Airport	Classification	Subclassification	Aircraft	Operator
., , , _ 0 1 1	Descent	Dallas/Fort Worth (DFW)	Air distribution system	Smoke	Boeing 737	American Airlines
		ical odor and fumes in the af ervice. Maintenance replaced			flight landed at DFW withou	t incident. The
1/11/2011	Climb	Fargo, North Dakota (FAR)	Cabin cooling system	Smoke	McDonnell Douglas DC-9	Delta Air Lines
election. Th		neapolis-St. Paul, the right air o manual control and the flighte re controller.				
1/11/2011	Climb	Dallas/Fort Worth (DFW)	_	Smoke	Embraer EMB-145LR	American Eagle Airlines
ver the wir		reported that, after the ice precrew declared an emergenc machine (ACM).				
1/17/2011	Descent	Newark, New Jersey (EWR)	Air distribution fan	Smoke	Boeing 737	US Airways
eference ha	andbook proced ft recirculation fa	n Flight Level (FL) 350, a fairly lures. The fumes subsided an ans and confirmed that the o	d the airplane was landed	at the nearest suital	ble airport, EWR. Maintenan	ce operated the
1/24/2011	Cruise	San Juan, Puerto Rico (SJU)	Air distribution system	Clogged	Boeing 767	US Airways
he situatio	n for about three	into the flight, a flight attend e minutes. The burning rubbe iced air circulation filters that	er odor became stronger.			
2/1/2011	Landing	_	Air distribution system	Smoke	Boeing 737	Southwest Airlin
		a burning plastic or rubber o replaced a recirculation fan.	dor in the front main cab	in. The pilots declare	d an emergency and contin	ued the landing.
2/2/2011	Takeoff	Las Vegas (LAS)	Auxiliary power unit oil system	Dirt/smoke	McDonnell Douglas DC-9	American Airline
		after takeoff. The pilots declar ervice. Technicians found exc				t incident. The
2/7/2011	Climb	Nashville, Tennessee (BNA)	Cabin cooling system	Smoke	Boeing 737	US Airways
		ht electric or plastic burning other incident. Maintenance of				
	Descent	_	Heating system	Smoke	Learjet 45	Charter
eturned to 2/8/2011 ollowing ir abin. An er Maintenanc	Descent nitial descent fro mergency desce e found the cocl	— m FL 430 and when passing nt was initiated, and after pa kpit heat temperature excess g to inputs in manual or auto	through FL 400, the flight ssing through FL 200, the ively high when running	crew noticed fumes smoke and fumes ra in manual mode. Fur	and smoke accumulating in pidly dissipated. A normal la ther troubleshooting found	the cockpit and anding was made.
eturned to 2/8/2011 ollowing ir abin. An er faintenanc ontrol valv	Descent itial descent fro nergency descent e found the coch e not respondin	nt was initiated, and after park kpit heat temperature excess	through FL 400, the flight ssing through FL 200, the ively high when running	crew noticed fumes smoke and fumes ra in manual mode. Fur	and smoke accumulating in pidly dissipated. A normal la ther troubleshooting found	the cockpit and anding was made.
eturned to 2/8/2011 ollowing ir abin. An er Maintenanc ontrol valv 2/21/2011	Descent nitial descent fro nergency desce e found the cocl e not respondin Climb re, smoke accom	nt was initiated, and after park kpit heat temperature excess	through FL 400, the flight ssing through FL 200, the ively high when running mode. The cockpit heat Auxiliary power unit core engine ered the cockpit. The smo	crew noticed fumes smoke and fumes ra in manual mode. Fur temperature control Smoke	and smoke accumulating in pidly dissipated. A normal la ther troubleshooting found valve was replaced. Bombardier Challenger CL-600 ared. Maintenance inspected	a the cockpit and anding was made. the cockpit heat Air Wisconsin Airlines
eturned to 2/8/2011 ollowing ir abin. An er Maintenanc ontrol valv 2/21/2011	Descent nitial descent fro nergency desce e found the cocl e not respondin Climb re, smoke accom	nt was initiated, and after parkpit heat temperature excess g to inputs in manual or auto — npanied by an acrid odor enti	through FL 400, the flight ssing through FL 200, the ively high when running mode. The cockpit heat Auxiliary power unit core engine ered the cockpit. The smo	crew noticed fumes rain manual mode. Fur temperature control Smoke ske subsequently clearly the no recurrence of	and smoke accumulating in pidly dissipated. A normal la ther troubleshooting found valve was replaced. Bombardier Challenger CL-600 ared. Maintenance inspected	a the cockpit and anding was made. the cockpit heat Air Wisconsin Airlines
eturned to 2/8/2011 ollowing in abin. An er flaintenance ontrol valv 2/21/2011 on departur bund glyco /7/2012 bout 3 ½ hrew donne	Descent nitial descent fro mergency descent e found the cock e not respondin Climb re, smoke accom I in the auxiliary Cruise nours into the flight d oxygen masks	nt was initiated, and after parkpit heat temperature excess g to inputs in manual or auto — npanied by an acrid odor enterpower unit area. The unit wa	through FL 400, the flight sising through FL 200, the ively high when running mode. The cockpit heat Auxiliary power unit core engine ered the cockpit. The smo is cleaned and operated w Air distribution system a strong chemical odor w with en route air traffic c	crew noticed fumes a smoke and fumes ra in manual mode. Fur temperature control Smoke ske subsequently cleavith no recurrence of Smoke while in cruise. They wontrol, followed by a	and smoke accumulating in pidly dissipated. A normal lather troubleshooting found valve was replaced. Bombardier Challenger CL-600 ared. Maintenance inspected smoke. Airbus A320 vere unable to determine its	a the cockpit and anding was made. the cockpit heat Air Wisconsin Airlines d the aircraft and Virgin America origin. The flight
eturned to 2/8/2011 collowing in abin. An er daintenance control valv 2/21/2011 an departur bund glyco /7/2012 bout 3 ½ hrew donne	Descent nitial descent fro mergency descent e found the cock e not respondin Climb re, smoke accom I in the auxiliary Cruise nours into the flight d oxygen masks	nt was initiated, and after parkpit heat temperature excess g to inputs in manual or auto panied by an acrid odor enterpower unit area. The unit water Tampa, Florida (TPA) ght, the flight crew detected and declared an emergency	through FL 400, the flight sising through FL 200, the ively high when running mode. The cockpit heat Auxiliary power unit core engine ered the cockpit. The smo is cleaned and operated w Air distribution system a strong chemical odor w with en route air traffic c	crew noticed fumes a smoke and fumes ra in manual mode. Fur temperature control Smoke ske subsequently cleavith no recurrence of Smoke while in cruise. They wontrol, followed by a	and smoke accumulating in pidly dissipated. A normal lather troubleshooting found valve was replaced. Bombardier Challenger CL-600 ared. Maintenance inspected smoke. Airbus A320 vere unable to determine its	a the cockpit and anding was made. the cockpit heat Air Wisconsin Airlines d the aircraft and Virgin America origin. The flight