



Flight Safety

D I G E S T

NOVEMBER 2004

RVSM Heightens
Need for Precision in
Altitude Measurement

Flight Safety Foundation

For Everyone Concerned With the Safety of Flight

www.flightsafety.org

OFFICERS AND STAFF

Chairman, Board of Governors	Hon. Carl W. Vogt
President and CEO	Stuart Matthews
Executive Vice President	Robert H. Vandel
Treasurer	James S. Waugh Jr.

ADMINISTRATIVE

Manager, Support Services	Linda Crowley Horger
----------------------------------	----------------------

FINANCIAL

Director of Finance and Administration	Crystal N. Phillips
Accountant	Millicent Wheeler

MEMBERSHIP

Director, Membership and Development	Ann Hill
Membership Services Coordinator	Ahlan Wahdan

PUBLICATIONS

Director of Publications	Roger Rozelle
Senior Editor	Mark Lacagnina
Senior Editor	Wayne Rosenkrans
Senior Editor	Linda Werfelman
Associate Editor	Rick Darby
Web and Print Production Coordinator	Karen K. Ehrlich
Production Designer	Ann L. Mullikin
Production Specialist	Susan D. Reed
Librarian, Jerry Lederer Aviation Safety Library	Patricia Setze

TECHNICAL

Director of Technical Programs	James M. Burin
Technical Programs Specialist	Joanne Anderson
Managing Director of Internal Evaluation Programs	Louis A. Sorrentino III
Q-Star Program Administrator	Robert Feeler
Manager, Data Systems and Analysis	Robert Dodd, Ph.D.
Manager of Aviation Safety Audits	Darol V. Holsman
Founder	Jerome Lederer 1902-2004

Flight Safety Foundation is an international membership organization dedicated to the continuous improvement of aviation safety. Nonprofit and independent, the Foundation was launched officially in 1947 in response to the aviation industry's need for a neutral clearinghouse to disseminate objective safety information, and for a credible and knowledgeable body that would identify threats to safety, analyze the problems and recommend practical solutions to them. Since its beginning, the Foundation has acted in the public interest to produce positive influence on aviation safety. Today, the Foundation provides leadership to more than 900 member organizations in more than 150 countries.

Flight Safety Digest

Vol. 23 No. 11

November 2004



In This Issue



1

RVSM Heightens Need for Precision in Altitude Measurement

Technological advances have honed the accuracy of aircraft altimeters, but false indications still can occur at any altitude or flight level. Some involve limitations of the altimeters themselves, but most are associated with the 'weak link' in altimetry — the human.

U.S. Hazardous-materials Incidents In Aviation Were Rarely Fatal

From 1994 through 2003, only the 1996 ValuJet accident resulted in fatalities during the transportation of hazardous materials by aircraft. Injuries in this incident category averaged about 20 per year.

STATS

23



26

Entropy Model of Accident Causation Proposed

Looking at organizational accident-risk factors in terms of the degradation of system factors is more effective than the human-error model, says an environmental health specialist.

Turbine Disk Fails During Departure

The accident report said that the uncontained engine failure resulted from fatigue cracks in an area damaged by shot-peening that had been performed either during the manufacture of the engine or during repairs.

BRIEFS

31

RVSM Heightens Need for Precision in Altitude Measurement

Technological advances have honed the accuracy of aircraft altimeters, but false indications still can occur at any altitude or flight level. Some involve limitations of the altimeters themselves, but most are associated with the ‘weak link’ in altimetry — the human.

— FSF EDITORIAL STAFF



Source: Innovative Solutions and Support

With the expanding use of reduced vertical separation minimum (RVSM) airspace, precise aircraft altitude information has become increasingly important. The reduction of standard vertical separation of aircraft to 1,000 feet/300 meters between Flight Level (FL) 290 (approximately 29,000 feet) and FL 410 means that deviation from an assigned flight level presents greater risks than existed with vertical separation of 2,000 feet/600 meters.

RVSM standards and advanced flight deck technology on transport category aircraft are designed to help minimize those risks (see “Global

Implementation of RVSM Nears Completion,” *Flight Safety Digest* Volume 23 [October 2004]). Nevertheless, hazards — involving malfunctioning instrument systems as well as human error — remain.

RVSM implementation has become possible in part because of improvements in the accuracy of modern altimeter systems, compared with the barometric (pressure) altimeters that were used in jet transports in the late 1950s (see “The Evolution of Altimetry Systems,” page 3).¹ Because the accuracy of conventional pressure altimeters is reduced at higher altitudes, the international standard established in

Altimeter system error can be exacerbated by inadequate operational practices by flight crews.

1960 was for vertical separation of 2,000 feet between aircraft operated above FL 290.

As technological advances in altimeters, autopilots and altitude-alerting systems led to more precision in measuring and maintaining altitude, the International Civil Aviation Organization (ICAO) determined, after a series of studies in the 1980s, that RVSM was technically feasible and developed a manual for RVSM implementation.² Further guidance for aircraft operators is contained in two ICAO-approved documents: European Joint Aviation Authorities Leaflet No. 6³ and U.S. Federal Aviation Administration Document 91-RVSM.⁴

Included in these documents are minimum equipment requirements for RVSM operations:

- Two independent altitude-measurement systems;
- One secondary surveillance radar transponder with an altitude-reporting system that can be connected to the altitude-measurement system in use for altitude-keeping;
- An altitude-alerting system; and,
- An automatic altitude-control system.

In addition, an ICAO minimum aircraft system performance specification (MASPS) requires that the altimetry systems in RVSM-approved aircraft have a maximum altimeter system error (ASE) of 80 feet/25 meters and that the automatic altitude-control systems must be able to hold altitude within 65 feet/20 meters. (ICAO defines ASE as “the difference between the altitude indicated by the altimeter display, assuming a correct altimeter barometric setting, and the pressure altitude corresponding to the undisturbed ambient pressure.”)

The ICAO manual for RVSM implementation says that before flight in RVSM airspace, a flight crew should conduct a ground check to ensure that the required two main altimeter systems are within the prescribed tolerances.

During flight, “generally flight crew operating procedures in RVSM airspace are no different than those in any other airspace,” the ICAO manual says.

Nevertheless, the manual says, “It is essential that the aircraft be flown at the cleared flight level (CFL). This requires that particular care be taken to ensure that air traffic control (ATC) clearances are fully understood and complied with. . . . During cleared transition between [flight] levels, the aircraft should not be allowed to overshoot or undershoot the new flight level by more than [150 feet/45 meters].”

In addition, flight crews should conduct regular hourly cross-checks between the altimeters, and “a minimum of two RVSM MASPS-compliant systems must agree within 60 meters (200 feet). Failure to meet this condition will require that the system be reported as defective and notified to ATC,” the ICAO manual says.

Height-monitoring is another RVSM requirement, and the U.K. Civil Aviation Authority (CAA) said in mid-2004 that height-monitoring had revealed the problem of “ASE drift,” a phenomenon in which, over time, most aircraft begin to fly lower than their displayed altitude.”⁵

U.K. CAA’s continuing investigation⁶ of ASE drift has found that likely causes include changes over time in the performance of air-data computers and erosion of pitot-static probes.

The investigation also has found that ASE can be exacerbated by inadequate operational practices by flight crews, especially noncompliance with aircraft operating restrictions contained in the RVSM airworthiness approval.

“In particular, if the approval was based on adherence to speed limits, the flight crew must be aware of those limits and ensure that the aircraft is operated within the cleared speed envelope,” U.K. CAA said.

In addition, during RVSM operations, both the active autopilot and the operating transponder should be selected to the same altimetry system, “unless there is a systems limitation or functionality which makes the requirement unnecessary and is detailed in the AFM [aircraft flight manual].”

Continued on page 5

The Evolution of Altimetry Systems

Altimeters have provided pilots with essential flight information since the development in 1928 of an accurate barometric (pressure) altimeter.

Altimeters indirectly measure the height of an aircraft above mean sea level or above a ground reference datum by sensing the changes in ambient air pressure that accompany changes in altitude and provide a corresponding altitude reading in feet or meters.

Static air pressure typically is derived from static sources mounted on the sides of the fuselage.


Figure 1 shows how the system typically works in early jet transports. A static line connects the static ports to the altimeter, mounted in an airtight case in which a sealed aneroid barometer reacts to changes in static air pressure. When static air pressure increases, the barometer contracts; when static air pressure decreases, the barometer expands. The movement of the barometer causes movement of height-indicating pointers, which present an altitude indication on the face of the altimeter.¹

Also on the face of a conventional barometric altimeter is a barometric scale, calibrated in hectopascals (hPa; millibars) or inches of mercury (in. Hg). The scale can be adjusted by a pilot to the local barometric pressure (e.g., within 100 nautical miles [185 kilometers]) or to standard barometric pressure — 1013.2 hPa or 29.92 in. Hg — as required by applicable regulations.

The system changed as new airplane models were introduced with air data computers and other advanced electronics and digital displays.

Figure 2 (page 4) shows how the system typically works in modern transport category aircraft, in which an air data inertial reference unit (ADIRU) is the primary source for altitude (as well as airspeed and attitude), and the information is displayed on the pilots' primary flight displays. Pitot and static pressures are measured by air data modules (ADMs) connected to three independent air pressure sources; ADM information is transmitted through data buses to the ADIRU. The ADIRU calculates altitude and airspeed by comparing information from the three sources, and provides a single set of data for both the captain and the first officer. If an


Figure 1
Typical Flight Instrumentation on Early Jet Transports



AC = Alternating current AI = Attitude indicator ALT = Altimeter ASI = Airspeed indicator

Source: Adapted from Carbaugh, David C. "Erroneous Flight Instrument Information." In *Enhancing Safety in the 21st Century: Proceedings of the 52nd Annual International Air Safety Seminar*. Alexandria, Virginia, U.S.: Flight Safety Foundation, 1999.

Figure 2
Typical Flight Instrumentation on Modern, Fly-by-wire Airplanes



ADIRU = Air data inertial reference unit ADM = Air data module AIMS = Airplane information management system ALT = Altimeter ASI = Airspeed indicator LCD = Liquid crystal display
 PFD = Primary flight display Ps = Static pressure Pt = Total pressure
 SAARU = Secondary attitude air data reference unit

Source: Adapted from Carbaugh, David C. "Erroneous Flight Instrument Information." In *Enhancing Safety in the 21st Century: Proceedings of the 52nd Annual International Air Safety Seminar*. Alexandria, Virginia, U.S.: Flight Safety Foundation, 1999.

ADIRU fails, an electronic standby altimeter and an electronic standby airspeed indicator receive pitot-static data from standby ADMs.²

The newest systems are "far more accurate" than the altimeters that were installed in early jet transports, said Jim Zachary, president of ZTI, an avionics consulting firm.³

"The old-type altimeters were not corrected for static source error, which is a function of airspeed," Zachary said. "The pilot would look at the altitude and look at the airspeed and go to some chart and say, 'OK, I've got to do this correction, change my altitude, add 100 feet or 200 feet.'

"That's all done automatically now. ... The new electronic altimeters have an integrated ADM and are connected to pitot (for airspeed) and static pneumatics. All errors are corrected internally. This is extremely important for the new, demanding

requirements for reduced separation of aircraft. ... It means that you have an altimeter that's absolutely correct." ■

— FSF Editorial Staff

Notes

1. Harris, David. *Flight Instruments and Automatic Flight Control Systems*. Oxford, England: Blackwell Science, 2004.
2. Carbaugh, Dave; Forsythe, Doug; McIntyre, Melville. "Erroneous Flight Instrument Information." *Boeing Aero No. 8* (October 1999).
3. Zachary, Jim. Telephone interview by Werfelman, Linda. Alexandria, Virginia, U.S. Nov. 12, 2004. Flight Safety Foundation, Alexandria, Virginia, U.S.

Air Data Computers, Glass-cockpit Displays Improve Accuracy

Despite the findings about ASE drift, the precision of altitude information available on the flight deck has increased in recent years because of the development of the air data computer (ADC), air data inertial reference unit (ADIRU) and digital displays. Modern systems may include an ADIRU that receives information from air data modules (ADMs) connected to the airplane's pitot probes and static pressure sources; the unit incorporates the best of that information (rejecting data that are incompatible with data produced by the other sources) to provide a single set of data to both pilots. Other standby ADMs provide information for standby flight instruments.^{7,8}

Improvements in the accuracy of modern altimeter systems, however, have not eliminated the possibility of critical altimeter-setting problems, which often result from human error.

Several factors related to barometric altimeters often have been associated with a flight crew's loss of vertical situational awareness, which in turn has been associated with many controlled-flight-into-terrain (CFIT) accidents.^{9,10} These factors include confusion resulting from the use of different altitude and height reference systems and different altimeter-setting units of measurement.

In 1994, the Flight Safety Foundation (FSF) CFIT Task Force said, "Flight crew training is now used as a means of solving this problem, but consideration should be given to discontinuing the use of some altimeter designs and standardizing the use of altitude and height reference systems and altimeter-setting units of measurement." Many of the Foundation's recommendations have since been endorsed by ICAO, civil aviation authorities and aircraft operators in many countries.

ICAO has recommended procedures for providing adequate vertical separation between aircraft and adequate terrain clearance, including what units should be used to measure air pressure, what settings should be used to display the measurement and when during a flight the settings

should be changed; nevertheless, many variations are used by civil aviation authorities in different countries (see "ICAO Prescribes Basic Principles for Vertical Separation, Terrain Clearance," page 6).¹¹

Capt. David C. Carbaugh, chief pilot, flight operations safety, Boeing Commercial Airplanes, said that, despite technological advances, "a human still has to set the altimeter, and it'll display what it's asked to display; if you ask it to display the wrong thing, that's what it will display. It's well-documented that the human is the weak link in altimetry."¹²

Altimeter mis-setting has been identified as one of the top six causal factors associated with level busts,¹³ which are defined by the European Organisation for Safety of Air Navigation (Eurocontrol) as unauthorized vertical deviations from an ATC flight clearance of more than 300 feet outside RVSM airspace and more than 200 feet within RVSM airspace.¹⁴

"Level busts, or altitude deviations, are a potentially serious aviation hazard and occur when an aircraft fails to fly at the level required for safe separation," Eurocontrol said in the "Level Bust Briefing Notes," a set of discussion papers included in the European Air Traffic Management *Level Bust Toolkit*. (The tool kit is designed to raise awareness of the level bust issue among aircraft operators and air navigation service providers and to help them develop strategies to reduce level busts. Fourteen briefing notes are a fundamental part of the tool kit.)

"When ... RVSM applies, the potential for a dangerous situation to arise is increased. This operational hazard may result in serious harm, either from a midair collision or from collision with the ground (CFIT)," the briefing notes said.

Studies have shown that an average of one level bust per commercial aircraft occurs each year, that one European country reports more than 500 level busts a year and that one major European airline reported 498 level busts from July 2000 to June 2002.¹⁵

“If you ask it [the altimeter] to display the wrong thing, that’s what it will display.”

Tzvetomir Blajev, coordinator of safety improvement initiatives, Safety Enhancement Business Division, Directorate of Air Traffic Management Programmes, Eurocontrol, said that data are not sufficient to evaluate incorrect altimeter settings in European RVSM airspace.¹⁶

Nevertheless, Blajev said, “An incorrect altimeter setting is of concern to us. ... Some of the 21 recommendations in the *Level Bust Toolkit* are designed to fight the risk of errors in altimeter settings. One

specifically is targeted at this: ‘Ensure clear procedures for altimeter cross-checking and approaching level calls.’ To support the implementation of this recommendation, we have developed a briefing note.”

Different Standards Lead to Confusion

Some altimeter-setting errors that occur during international flights have

been attributed to the fact that not all civil aviation authorities have the same altimeter-setting rules and requirements.

C. Donald Bateman, chief engineer, flight safety systems, Honeywell, said, “We have so many different altimeter-setting standards. Obviously, there’s a good chance we’re going to have errors, and we’ve had them.”¹⁷

For example, different altimeter-setting practices involving QFE and QNH can cause confusion.

ICAO Prescribes Basic Principles for Vertical Separation, Terrain Clearance

The International Civil Aviation Organization (ICAO) recommends a method of providing adequate vertical separation between aircraft and adequate terrain clearance, according to the following principles:¹

- “During flight, when at or below a fixed altitude called the transition altitude, an aircraft is flown at altitudes determined from an altimeter set to sea level pressure (QNH)² and its vertical position is expressed in terms of altitude;
- “During flight, above the transition altitude, an aircraft is flown along surfaces of constant atmospheric pressure, based on an altimeter setting of 1013.2 hectopascals [29.92 inches of mercury], and throughout this phase of a flight, the vertical position of an aircraft is expressed in terms of flight levels. Where no transition altitude has been established for the area, aircraft in the en route phase shall be flown at a flight level;
- “The change in reference from altitude to flight levels, and vice versa, is made, when climbing, at the transition altitude and, when descending, at the transition level;
- “The adequacy of terrain clearance during any phase of a flight may be maintained in any of several

ways, depending upon the facilities available in a particular area, the recommended methods in the order of preference being:

- “The use of current QNH reports from an adequate network of QNH reporting stations;
- “The use of such QNH reports as are available, combined with other meteorological information such as forecast lowest mean sea level pressure for the route or portions thereof; and,
- “Where relevant current information is not available, the use of values of the lowest altitudes of flight levels, derived from climatological data; and,
- “During the approach to land, terrain clearance may be determined by using the QNH altimeter setting (giving altitude) or, under specified circumstances ... a QFE³ setting (giving height above the QFE datum).”

ICAO says that these procedures provide “sufficient flexibility to permit variation in detail[ed] procedures which may be required to account for local conditions without deviating from the basic procedures.” ■

— FSF Editorial Staff

Notes

1. International Civil Aviation Organization. *Procedures for Air Navigation Services. Aircraft Operations, Volume 1: Flight Procedures. Part VI, Altimeter Setting Procedures.*
2. QNH is the altimeter setting provided by air traffic control or reported by a specific station and takes into account height above sea level with corrections for local atmospheric pressure. On the ground, the QNH altimeter setting results in an indication of actual elevation above sea level; in the air, the QNH altimeter setting results in an indication of the true height above sea level, without adjustment for nonstandard temperature.
3. QFE is an altimeter setting corrected for actual height above sea level and local pressure variations; a QFE altimeter setting applies to a specific ground-reference datum. On the ground, a correct QFE altimeter setting results in an indication of zero elevation; in the air, the QFE setting results in an indication of height above the ground reference datum.

QFE is an altimeter setting corrected for actual height above sea level and local pressure variations; a QFE altimeter setting applies to a specific ground-reference datum. On the ground, a correct QFE setting results in an indication of zero elevation; in the air, the QFE setting results in an indication of height above the ground-reference datum.

QNH is the altimeter setting provided by ATC or reported by a specific station and takes into account height above sea level with corrections for local atmospheric pressure. On the ground, the QNH altimeter setting results in an indication of actual elevation above sea level; in the air, the QNH altimeter setting results in an indication of the true height above sea level, without adjustment for nonstandard temperature.

(Another “Q code” is QNE, which refers to the standard pressure altimeter setting of 1013.2 hectopascals [hPa], or 29.92 inches of mercury [in. Hg].)


Some operators require flight crews to set the altimeter to QFE in areas where QNH is used by ATC and by most other operators.

The FSF Approach-and-landing Accident Reduction (ALAR) Task Force said that using QNH has two advantages: “eliminating the need to change the altimeter setting during operations below the transition altitude/flight level” and eliminating “the need to change the altimeter setting during a missed approach.” (Such a change usually is required when QFE is used.)¹⁸

Many civil aviation authorities use hectopascals (millibars), to measure barometric pressure; others use inches of mercury (Figure 1); if a pilot confuses the two and mis-sets the altimeter, the result can mean that the aircraft is hundreds of feet lower (or higher) than the indicated altitude (Figure 2; Figure 3, page 8).¹⁹


The ICAO standard is for altimeter settings to be given in hectopascals, and in

Figure 1
Altimeter-setting Conversion Table




Source: U.S. Government Printing Office

Figure 2
Pressure/Altitude Conversion Table



*Standard Atmosphere
Source: U.S. Government Printing Office

Figure 3
Effect of an Altimeter Mis-set to Inches, Rather Than Hectopascals



AFL = Above field level MSL = Mean sea level Hg = Mercury hPa = Hectopascals
 QNH = Altimeter setting that causes altimeter to indicate height above mean sea level (thus, field elevation at touchdown)

Source: Flight Safety Foundation Approach-and-landing Accident Reduction (ALAR) Task Force

1994, the Foundation recommended that all civil aviation authorities adopt hectopascals for altimeter settings to eliminate the “avoidable hazard of mis-setting the altimeter.”²⁰

In 2000, the Foundation repeated the recommendation in its “ALAR Briefing Notes”:

When in. Hg is used for the altimeter setting, unusual barometric pressures, such as a 28.XX in. Hg (low pressure) or a 30.XX in. Hg (high pressure), may go undetected when listening to the ... ATIS [automatic terminal information service] or ATC, resulting in a more usual 29.XX altimeter setting being set.

Figure [4, page 9] and Figure [5, page 10] show that a 1.00 in. Hg discrepancy in the altimeter setting results in a 1,000-foot error in the indicated altitude.

In Figure [4], QNH is an unusually low 28.XX in. Hg, but the altimeter was set mistakenly to a more usual 29.XX in. Hg, resulting in the true

altitude (i.e., the aircraft’s actual height above mean sea level) being 1,000 feet lower than indicated.

*In Figure [5], QNH is an unusually high 30.XX in. Hg, but the altimeter was set mistakenly to a more usual 29.XX in. Hg, resulting in the true altitude being 1,000 feet higher than indicated.*²¹

Numerous reports about these problems have been submitted to the U.S. National Aeronautics and Space Administration (NASA) Aviation Safety Reporting System (ASRS),²² including the following:


- The captain of an air carrier passenger flight said that during descent to Frankfurt, Germany, “the altimeters were incorrectly set at 29.99 in. Hg instead of 999 hPa, resulting in Frankfurt approach control issuing an altitude alert. The reason I believe this happened is that the ATIS was copied by the relief pilot using three digits with a decimal point. Since Frankfurt normally issues both hectopascals and inches of mercury on the ATIS,

I incorrectly assumed that the decimal denoted the inches of mercury scale and announced ‘2999’ and set my altimeter. The first officer did the same. ... In the future, I will insist that all ATIS information is to be copied, and particularly both altimeter settings.

“ ... Safety would also be greatly enhanced if ICAO standards were complied with by the controllers (i.e., stating the units when giving the altimeter setting). ... I believe this could happen to almost any pilot, given similar circumstances. I feel that stating units by all concerned would eliminate most of the problem”;²³

- Another pilot said that at the end of a long overwater flight, “approach control gave the altimeter as 998 hPa. I read back 29.98 [in. Hg]. [The] approach controller repeated his original statement. Forgetting that our altimeters have settings for millibars and hectopascals (which I had only used once in my career, and that was six months ago), I

Figure 4
Effect of a One-inch-high Altimeter Setting



AFL = Above field level MSL = Mean sea level Hg = Mercury
 QNH = Altimeter setting that causes altimeter to indicate height above mean sea level (thus, field elevation at touchdown)

Source: Flight Safety Foundation Approach-and-landing Accident Reduction (ALAR) Task Force

asked where the conversion chart was. ‘Old hand’ captain told me that approach [control] meant 29.98 [in. Hg]. Assuming that he knew what he was doing, I believed him. We were a bit low on a ragged approach, and I knew we were awfully close to some of the hills that dot the area ... but it was not until we landed and our altimeters read 500 feet low that I realized what had happened.”²⁴

Transition Altitudes Vary

Civil aviation authorities worldwide have established transition altitudes at which flight crews switch their altimeter settings between the standard altimeter setting for flights at or above the transition altitude and the altimeter setting being reported by the nearest reporting station for flights below the transition altitude. The designated transition altitude varies from 3,000 feet in Buenos Aires, Argentina, to 18,000 feet in North America.²⁵ Transition altitudes can be specified for entire countries or for smaller areas, such as individual airports; in some jurisdictions, the

transition altitude varies, depending on QNH.

NASA said that numerous ASRS reports have been submitted involving altimeter mis-setting events at transition altitudes. The reports included the following:

- A flight crew on an air carrier cargo flight in Europe said that they forgot to reset their altimeters at the unfamiliar transition altitude of 4,500 feet. “Climbing to FL 60 ... we were task-saturated flying the standard instrument departure, reconfiguring flaps and slats, resetting navigation receivers and course settings, resetting engine anti-ice, etc. The crew missed resetting the Kollsman [barometric altimeter] window to 29.92 [in. Hg] at 4,500 feet MSL [above mean sea level] and leveled off at FL 60 indicated altitude with a Kollsman setting of 28.88 [in. Hg]. Departure [control] informed us of our error”;²⁶
- A first officer on an air carrier passenger flight said, “Due to a distraction from a flight attendant, we

neglected to reset altimeters passing through FL 180 from 29.92 [in. Hg] to 29.20 [in. Hg]. Extremely low pressure caused us to be at 12,200 feet when we thought we were at 13,000 feet. The controller queried us; we realized our error and climbed to 13,000 feet after resetting the altimeter. We didn’t accomplish the approach checklist on descent, which would have prevented this”;²⁷

- A first officer on an air carrier cargo flight said, “Received low-altitude warning, pulled up and discovered altimeter ... was mis-set. Altimeter was set at 29.84 [in. Hg] and should have been set at 28.84 [in. Hg]. Crew distracted with a [mechanical problem] about the time of altimeter transition [through FL 180]”;²⁸ and,
- A first officer on an air carrier passenger flight said, “Just before we began descent, the flight attendant brought up dinner for both of us at the same time. Started descent as [we] started eating. Because of distraction, we failed to reset altimeters at 18,000 feet.

Descended to 17,000 feet with wrong altimeter setting. Resulted in level-off 300 feet below assigned altitude. Received [traffic advisory] of traffic at 16,000 feet. Controller suggested that we reset altimeters.”²⁹

ASRS said, “The cure ... is strict adherence to checklists and procedures (sterile cockpit,³⁰ readback of ATC clearances, etc.) and good CRM [crew resource management] techniques for cross-checking with the other crewmember(s).”

Another element that sometimes introduces confusion is the use of metric altitudes in some countries (for example, in Russia and China). The FSF “ALAR Briefing Notes” said that this requires standard operating procedures (SOPs) for the use of metric altimeters or conversion tables.³¹

The “ALAR Briefing Notes” said that, in general, to prevent many altimeter-setting errors associated with different units of measurement or extremes in barometric pressure, the following SOPs should be used “when broadcasting (ATIS or controllers) or reading back (pilots) an altimeter setting:

- “All digits, as well as the unit of measurement (e.g., *inches* or *hectopascals*) should be announced.

“A transmission such as ‘altimeter setting six seven’ can be interpreted as 28.67 in. Hg, 29.67 in. Hg, 30.67 in. Hg or 967 hPa.

“Stating the complete altimeter setting prevents confusion and allows detection and correction of a previous error; [and,]


- “When using in. Hg, ‘low’ should precede an altimeter setting of 28.XX in. Hg, and ‘high’ should precede an altimeter setting of 30.XX in. Hg.”³²

Fatigue, Heavy Workloads Contribute to Mis-setting Errors

An ASRS report on international altimetry said that several factors appear to increase the possibility of altimeter-setting errors:

- Fatigue, which may result from lengthy international flights;
- Heavy workloads during approach, especially when transition altitudes are relatively low. “Obtaining altimeter settings and landing data closer to the approach

Figure 5
Effect of a One-inch-low Altimeter Setting



AFL = Above field level MSL = Mean sea level Hg = Mercury
 QNH = Altimeter setting that causes altimeter to indicate height above mean sea level (thus, field elevation at touchdown)

Source: Flight Safety Foundation Approach-and-landing Accident Reduction (ALAR) Task Force

segment complicates the task of preparing data for landing at the very time the flight crew may be most fatigued”;

- Language difficulties, including “rapid delivery of clearances . . . , unfamiliar accents and contraction of hPa (hectopascals) or mb (millibars). . . . Other flight crews communicating in their native [languages] contribute to a lack of awareness of what other traffic is doing”;
- Communication procedures in which one person receives approach and landing information and conveys the information to the rest of the flight crew. This procedure “means that a misconception or misunderstanding is less likely to be detected until too late”;
- Cockpit management, which “often [provides] inadequate crew briefing for approach and landing, with no mention of how the altimeter setting will be expressed — that is, [inches of mercury], [millibars] or [hectopascals]. Flight crews also may not adequately review approach charts for information. Some airlines do not provide the second officer with approach [charts]; unless he or she makes an extra effort to look at one of the pilot’s charts, the altimeter-setting standard may be unknown.” (In addition, some airlines provide only one set of approach charts for the captain and first officer to share.)³³

The ASRS report contained several recommendations, including having each flight crewmember “pay particular attention” during the review of approach charts before the descent to whether altimeter settings will be given in inches, millibars or hectopascals; ensuring that the approach briefing includes mention of how the altimeter setting will be expressed; enabling more than one flight crewmember to hear ATC clearances and ATIS messages; and complying with proper crew coordination standards by cross-checking other crewmembers for accurate communication and procedures.

‘Odd’ Altimeter Settings Should Prompt Questions

Some of the most frequent errors involving incorrect altimeter settings occur because

the barometric pressure is unusually high or unusually low — and because when pilots hear the unexpected altimeter settings, they inadvertently select the more familiar altimeter settings that they had expected. The result can be that an aircraft is hundreds of feet lower (or higher) than the indicated altitude.

For example, in a report submitted to ASRS, the first officer of an air carrier cargo flight described the following event, which occurred in December 1994, during approach to Anchorage, Alaska, U.S., after a flight from Hong Kong:

Destination weather [included an altimeter setting of] 28.83 [in. Hg]. Prior to initial descent, the second officer received and put the ATIS information on the landing bug card, except that the altimeter was written as 29.83 [in. Hg]. We were initially cleared to 13,000 feet. I repeated the descent clearance and gave the altimeter as 29.83 [in. Hg]. Center did not catch this in my readback. [On final approach], the second officer noticed the radio altimeter at 800 feet and the barometric altimeter at approximately 1,800 feet. . . . The captain started a go-around at the same time the tower reported they had a low-altitude alert warning from us. . . . As we taxied, we heard the tower tell another aircraft they had a low-altitude alert. . . . Was this [due] to an improper altimeter setting, too?³⁴

ASRS said that reports involving unexpected altimeter settings are filed “in bunches, as numerous flight crews experience the same problem on the same day in a particular area that is encountering unusual barometric pressures.”³⁵

Other errors occur when pilots misunderstand altimeter settings they receive from ATC or incorrectly copy an altimeter setting. The following ASRS reports are examples:

- “The 30.06 [in. Hg] altimeter setting we used was actually the wind speed and direction and was written [as] 3006,” a Boeing 767 first officer said. “In my mind, this was a reasonable

Errors occur when pilots misunderstand altimeter settings they receive from ATC or incorrectly copy an altimeter setting.

altimeter setting. The ATIS setting was actually 29.54 [in. Hg]”;³⁶

- “The altimeter [setting] was 28.84 [in. Hg],” the second officer on a cargo flight said. “I remember enlarging the 8s with two circles on top of each other, thinking this would be sufficient in drawing attention to the low altimeter setting. The next crew after our flight found the altimeter to be set at 29.84 [in. Hg] instead of the actual 28.84 [in. Hg] setting”;³⁷ and,
- “The pilot not flying understood [the] ATIS recording to state altimeter setting to be 29.99 [in. Hg] when actually the setting was 29.29 [in. Hg],” the captain of an MD-83 passenger flight said. He suggested that “slower, more pronounced ATIS recordings” might help avoid similar problems.³⁸

Some controllers emphasize the altimeter setting when the barometric pressure is unusually low, but typically this is not a requirement.

Altimeter Design Can Cause Mis-reading of Indicator

Sometimes, even though the altimeter setting has been selected correctly, errors occur in reading an altimeter. In 1994, the Foundation included among its recommendations to reduce the worldwide CFIT accident rate a request that ICAO issue a warning against the use of three-pointer altimeters and drum-pointer altimeters.

In some incidents, flight crews operate without the most current altimeter settings.

“The misreading of these types of altimeters is well documented,” the Foundation said.³⁹

In 1998, ICAO adopted amendments to its standards and recommended practices to prohibit the use of these altimeters in commercial aircraft operated under instrument flight rules (IFR), citing a “long history of misreadings.”⁴⁰

Before the adoption of those amendments, a Nov. 14, 1990, accident occurred in which an Alitalia McDonnell Douglas DC-9-32 struck

a mountain during a night instrument landing system (ILS) approach to Kloten Airport in Zurich, Switzerland. The accident report said that, among other problems, the flight crew “probably misread the [drum-pointer] altimeter during the approach and hence did not realize that the aircraft was considerably below the glide path.” The airplane was destroyed, and all 46 people in the airplane were killed.⁴¹

The report said that drum-pointer altimeters are “less easy to read correctly, especially during periods of high workload” than other altimeters. “A quick look after being distracted can usually induce a reading 1,000 feet off, if the barrel drum is halfway between thousands,” the report said.

In a report submitted to ASRS, the single pilot of a small corporate airplane described a similar altimeter-reading problem:

I was assigned 5,000 feet [by ATC]. I thought I was getting ready to level off at 5,000 feet, and departure [control] asked what altitude I was climbing to. I realized I was at 5,700 feet instead of 4,700 feet. This altimeter [makes it] difficult to tell sometimes what the altitude is because the 1,000-foot indicators are in a window to the left. No excuse. I simply looked at it wrong. I know it is difficult to read, so I should have been more alert.”⁴²

In some incidents, especially when barometric pressure is fluctuating, flight crews operate without the most current altimeter settings.

For example, the crew of an American Airlines McDonnell Douglas MD-83 was conducting a very-high-frequency omnidirectional radio (VOR) approach to Bradley International Airport in Windsor Locks, Connecticut, U.S., in night instrument meteorological conditions (IMC) on Nov. 12, 1995, when the first officer glanced at the altimeter and observed that the airplane was below the minimum descent altitude. He told the captain, who was the pilot flying. Moments later, the airplane struck trees on a ridge about 2.5 nautical miles (4.6 kilometers) northwest of the approach end of the runway. The captain began a go-around, applying all available power; the airplane struck the localizer antenna array at the end of a safety overrun area, landed on a stopway and rolled down the runway.⁴³

The airplane received minor damage. One passenger received minor injuries; the 77 other people in the airplane were not injured.

When the accident occurred, the indicated altitude on the altimeter, using the QFE method, was “about 76 feet too high ... resulting in the airplane being 76 feet lower than indicated on the primary altimeters,” the U.S. National Transportation Safety Board said in the final report on the accident. The report said that the probable cause of the accident was “the flight crew’s failure to maintain the required minimum descent altitude until the required visual references identifiable with the runway were in sight.” Contributing factors were “the failure of the ... approach controller to furnish the flight crew with a current altimeter setting, and the flight crew’s failure to ask for a more current setting.”

Occasionally, in remote areas, flights are conducted far from weather-reporting stations. Rarely, the altimeter setting provided by ATC is inaccurate.

The pilot of a small business airplane said that, as he was flying his airplane near Lake Michigan, U.S., at an indicated altitude of 17,000 feet, ATC “reported my altitude encoder indicated 16,000 feet on the readout. I had departed [under visual flight rules] and picked up my IFR clearance at about 4,000 feet. ... I had set the [altimeter setting] as provided by [ATC] when clearance was provided. I was approaching a cold front, which was lying north to south over Lake Michigan. I asked for an altimeter setting. The setting provided was one inch lower than the previously provided setting (about 100 nautical miles [185 kilometers] earlier). I reset my altimeter. ... After the reset, my altimeter now indicated 16,000 feet ... The problem was evidently a very steep pressure gradient behind the cold front.”⁴⁴

In 1997, ASRS reviewed its database, as well as accident reports and incident reports of the Canadian Aviation Safety Board (predecessor of the Transportation Safety Board of Canada), and found that most altimeter mis-setting incidents that occurred during periods of extremely low barometric pressure occurred in very cold locations or in areas known for severe weather and unusual frontal systems. A number of reports were

filed from northern Europe, including Brussels, Belgium; Copenhagen, Denmark; Frankfurt, Germany; Keflavik, Iceland; and Moscow, Russia.⁴⁵

Temperature Errors Sometimes Are Overlooked

Just as pilots adjust the altimeter settings for nonstandard air pressure, a correction also is required — in some situations — for nonstandard air temperature. When the air temperature is warmer than the standard temperature for a specific height in the atmosphere, the true altitude is higher than the altitude indicated on the altimeter. When the air temperature is colder than the standard temperature, the true altitude is lower than the indicated altitude. Moreover, in extremely cold temperatures, the true altitude may be several hundred feet lower (Figure 6, page 14).

ICAO says that when the ambient temperature on the surface is “much lower than that predicted by the standard atmosphere,” a correction must be made, and the calculated minimum safe altitudes must be increased accordingly.

“In such conditions, an approximate correction is 4 percent height increase for every 10 degrees Celsius (C) below the standard temperature, as measured at the altimeter-setting source,” ICAO says. “This is safe for all altimeter-setting source altitudes for temperatures above minus 15 degrees C [five degrees Fahrenheit (F)].”⁴⁶

ICAO says that for colder temperatures, temperature-correction tables should be used.

ICAO’s temperature-correction table shows, for example, that if the ambient temperature on the surface is minus 20 degrees C (minus 4 degrees F), and the airplane is being flown 1,000 feet above the altimeter-setting source, the pilot should add 140 feet to published procedure altitudes; at 5,000 feet, the pilot should add 710 feet (Table 1, page 15).

Typically, operators should coordinate the handling of cold-temperature altitude corrections

A correction
is required — in
some situations
— for nonstandard
air temperature.

with ATC facilities for each cold-weather airport or cold-weather route in their system. The operators should confirm that minimum assigned flight altitudes/flight levels and radar vectoring provide adequate terrain clearance in the event of the coldest expected temperatures; should develop cold-weather altitude-correction procedures, including an altitude-correction table; and should determine which procedures or routes have been designed for cold temperatures and can be flown without altitude corrections.⁴⁷

The flight crew training manual for Boeing 737-300/400/500 airplanes says that operators “should consider altitude corrections when altimeter errors become appreciable, especially where high terrain and/or obstacles exist near airports in combination with very cold temperatures (minus 30 degrees C/minus 22 degrees F, or colder). Further, operators should also consider correcting en route minimum altitudes and/or flight levels where terrain clearance is a factor. ... For very cold temperatures, when flying published minimum altitudes significantly above the airport, altimeter errors can exceed 1,000 feet,

resulting in potentially unsafe terrain clearance if no corrections are made.”

In one reported occurrence, a McDonnell Douglas MD-80 was flown to Kelowna, British Columbia, Canada, when the surface temperature in Kelowna was minus 27 degrees C (minus 17 degrees F). The crew received clearance for a nonprecision approach; soon afterward, the crew abandoned the approach and asked ATC for radar vectors for another nonprecision approach, flew the approach and landed the airplane. Later, flight crewmembers told other pilots that they had abandoned the first approach after they realized that they had not applied the necessary 800-foot cold-temperature correction to the published procedure-turn altitude of 4,900 feet above field elevation. A ground-proximity warning system (GPWS) terrain warning occurred near a mountain east of the localizer; the airplane flew over the mountaintop with a clearance of 150 feet.⁴⁸

Despite the technological advances in aircraft altimetry and airspeed systems, static ports and pitot probes still are required. Blockages in the




Table 1
Cold-temperature Altitude Correction Chart

Airport temperature (degrees Celsius/Fahrenheit)	Height above the elevation of the altimeter setting source (feet)													
	200	300	400	500	600	700	800	900	1,000	1,500	2,000	3,000	4,000	5,000
0/32	20	20	30	30	40	40	50	50	60	90	120	170	230	280
-10/14	20	30	40	50	60	70	80	90	100	150	200	290	390	490
-20/-4	30	50	60	70	90	100	120	130	140	210	280	420	570	710
-30/-22	40	60	80	100	120	140	150	170	190	280	380	570	760	950
-40/-40	50	80	100	120	150	170	190	220	240	360	480	720	970	1,210
-50/-58	60	90	120	150	180	210	240	270	300	450	590	890	1,190	1,500

Source: International Civil Aviation Organization

pitot-static system still occur, and accidents can result (see “Technological Advances Haven’t Eliminated Pitot-static System Problems,” page 16).

These blockages most frequently occur while an airplane is on the ground, sometimes because of tape that is placed over static ports during maintenance and not removed afterward, or because of water that enters and becomes trapped in static lines and then freezes when the airplane is flown into colder temperatures at higher altitudes. Typically, the problem does not become apparent to the flight crew until after takeoff; even then, they may experience considerable confusion about conflicting information available from their flight instruments.

Altitude Information Comes From Other Sources

Other systems, including radio altimeters and the geometric altitude component of terrain awareness and warning systems (TAWS)⁴⁹ and navigation systems based on the global positioning system (GPS), also provide altitude information.

Radio altimeters, which typically are used below 2,500 feet above ground level during approaches and landings, measure the vertical distance between an aircraft and the ground directly beneath it. They function this way: The radio altimeter’s transmitter beams a radio signal downward; the signal is reflected by the ground to the radio altimeter’s receiver. The received frequency differs from the transmitted

frequency, and that difference varies according to aircraft height and the time required for the signal to travel from the airplane to the ground and back. The frequency difference is used in calculating the height of the aircraft above the ground.⁵⁰

The radio altimeter is designed to be accurate, plus or minus one foot, or plus or minus 3 percent of the indicated height above the ground, whichever is larger. Errors can be introduced by reflections from the landing gear or other parts of the aircraft, uneven terrain and large buildings or trees.

The geometric altitude component of TAWS measures the aircraft’s true altitude and is computed by blending “component altitudes,” such as GPS altitude, radio altitude and QNH-corrected barometric altitude; the computation also compensates for errors caused by nonstandard air temperatures.

Geometric altitude is included on the TAWS terrain-awareness display to provide the flight crew with a reference altitude for the display and for terrain-avoidance alerts — not for vertical navigation.

A study by Honeywell of the effects of including a digital readout of geometric altitude on the terrain awareness display resulted in findings that included the following:⁵¹

- “An EGPWS [enhanced ground-proximity warning system] that employs geometric altitude as the reference altitude for the

Continued on page 19

Technological Advances Haven't Eliminated Pitot-static System Problems

Despite many technological advances that have led to the development of aircraft systems capable of precise altitude and airspeed measurements, conventional pressure altimeters and airspeed indicators depend on simple static ports and pitot probes to function correctly. Pitot-static system problems continue to occur and — rarely — become factors in accidents.

“The fact that these accidents occur infrequently can contribute to the ‘startle’ factor [that] flight crews experience, leaving them uncertain about how to respond to the anomaly,” said Capt. David C. Carbaugh, chief pilot, flight operations safety, Boeing Commercial Airplanes.¹

One such accident involved an Aeroperu Boeing 757-200 that struck the Pacific Ocean off the coast of Lima, Peru, on Oct. 2, 1996, about 30 minutes after takeoff from Jorge Chavez International Airport in Lima on a night flight to Santiago, Chile. The airplane was destroyed, and all 70 people in the airplane were killed.² The flight crew had realized immediately after liftoff that their altimeters and airspeed indicators were not providing correct information and had declared an emergency, but they were unable to diagnose the problem and to safely land the airplane.

The final report by the Peruvian General Director of Air Transport Commission of Accident Investigations said that the probable cause of the accident was adhesive tape that was not removed from the static ports after maintenance; the captain did not observe the tape during his walk-around preflight inspection.

The report said that during the takeoff roll, airspeed indications and altitude indications were normal; afterward, however, altimeter indications increased too slowly, and the indicated airspeed (IAS) was too slow. A wind shear warning was activated three times, although wind was relatively calm and there was no

significant weather. The ground-proximity warning system repeatedly sounded warnings of “TOO LOW TERRAIN” and “SINK RATE.”

About one minute before the airplane struck the water, as the “TOO LOW TERRAIN” warning sounded, there was no reaction from the crew, who believed an altimeter indication that the airplane was at 9,700 feet.

The report said that the cockpit voice recorder showed that the captain was “confused in his reactions ... and [hesitant] with his commands,” while the first officer displayed “equivalent confusion.” Neither pilot identified the cause of the problem.

Erroneous airspeed indications have been cited in several accidents, including a Feb. 6, 1996, accident in which a B-757-200 struck the Caribbean Sea off the northern coast of the Dominican Republic about five minutes after takeoff from Gregorio Luperon International Airport in Puerto Plata for a flight to Frankfurt, Germany. The airplane — which was operated by Birgenair, a charter company in Istanbul, Turkey, for Alas Nacionales, a Dominican airline — was destroyed, and all 189 occupants were killed.³

In the final report, the Dominican Junta Investigadora de Accidentes Aéreos said that the probable cause of the accident was “the failure on the part of the flight crew to recognize the activation of the stick shaker as an imminent warning of [an] aerodynamic stall and their failure to execute proper procedures for recovery [from] the control loss.”

The report said, “Before activation of the stick shaker, confusion of the flight crew occurred due to the erroneous indication of an increase in airspeed [on the captain’s airspeed indicator] and a subsequent overspeed warning.”

The erroneous airspeed indication and the erroneous overspeed warning resulted

from an obstruction of the airplane’s upper-left pitot tube.

The report said that the airplane had not been flown for 20 days before the accident and that, during that time, routine maintenance had been performed, including an inspection and ground test of the engines. Investigators believed that engine covers and pitot covers were not installed before or after the ground test.

During the takeoff roll, the captain determined that his airspeed indicator was not working; four other sources of airspeed information were available, and he continued the takeoff “contrary to the established procedures,” the report said.

During climbout, the crew decided that the captain’s airspeed indicator and the first officer’s airspeed indicator were providing incorrect indications and that the alternate airspeed indicator was providing correct information. Nevertheless, none of the three flight crewmembers (the captain, the first officer and a relief captain) suggested “the appropriate course of action to compare the indications or to switch the instrument selector [to the alternate source] to derive airspeed information from the [first officer’s air data computer] and its pitot system,” the report said.

The wreckage of the airplane was not recovered, and the cause of the pitot-system obstruction was not determined, but the report said that the obstruction likely resulted from “mud and/or debris from a small insect that was introduced in the pitot tube during the time the aircraft was on the ground in Puerto Plata.”

Pitot-static System Problems Have Many Causes

Other aircraft accident reports and incident reports have identified numerous causes of malfunctions in static ports and pitot probes, including

disconnected or leaking static lines or pitot lines, trapped water in static lines or pitot lines, icing of static ports or pitot probes, blockage of static ports or pitot probes by insects, static-port covers or pitot-probe covers that were not removed before flight, and static-port drain caps that were not replaced following maintenance.^{4,5}

“Even the fancy new pitot-static systems still have a probe that sticks out into the airflow, and they still require information from the probe,” Carbaugh said.

The incorrect information also affects other aircraft systems or indicators. For example, terrain awareness and warning system (TAWS)⁶ information may be unavailable, overspeed warnings and wind shear warnings may be unreliable, and engine indication and crew alerting system messages may not identify the basic source of the problem (Table 1). Other aircraft systems and indicators are unaffected, including pitch and roll indicators, radio altimeters (within

the normal activation limits) and radio navigation aid signals (Table 2, page 18).

If a blockage occurs in the static system, erroneous altitude indications and airspeed indications can result. The altitude indicator operates correctly during the takeoff roll. After liftoff, however, the altitude indicator remains at the field elevation (assuming that the initial altimeter setting indicated the field elevation). The static-port blockage causes erroneous airspeed indications following liftoff, when the airspeed indicator lags behind the actual airspeed during climb. The vertical speed indicator (VSI) stops indicating a rate of climb or descent.

If a blockage occurs that traps pressure in a pitot probe, the airspeed indicator does not move from its lower stop during the takeoff roll. After liftoff, the airspeed indication begins to increase, and continues increasing as altitude increases; the airspeed indication may appear to exceed the maximum operating limit speed (V_{MO}) and may result in an

overspeed warning. During climb, the altimeter and the VSI function correctly, for practical purposes. If a blockage occurs in the pitot probe’s ram inlet while the water drain hole is unobstructed, pressure in the pitot tube may escape; in this event, the airspeed indication decreases to zero.

In incidents involving erroneous altitude indications and erroneous airspeed indications, the problem must be diagnosed promptly by flight crews, and recovery techniques must be initiated immediately.

“The longer erroneous flight instruments are allowed to cause a deviation from the intended flight path, the more difficult the recovery will be,” Carbaugh said. “Some basic actions are key to survival.”

“Regardless of the situation, good communication between crewmembers is essential, and several basic actions are paramount:

- “Recognizing an unusual or suspect indication;

Table 1
Reliable Information/Systems With Pitot-static System Malfunction

System/Indicator	Notes
Pitch and roll	
Engine thrust	No engine pressure ratio, use engine low-pressure rotor (fan) speed
Radio altitude	When within normal activation limits
Basic ground-proximity warning system	(Initial versions of terrain awareness and warning system may not be reliable)*
Terrain awareness and warning system with geometric altitude	(Initial versions of terrain awareness and warning system may not be reliable)
Stick shaker	May not always be available, but reliable if activated
Groundspeed	Uses inertial information
Airplane position	Uses inertial information
Track and heading	
Radio navigation aid signals	

* Terrain awareness and warning system (TAWS) is the term used by the European Joint Aviation Authorities and the U.S. Federal Aviation Administration to describe equipment meeting International Civil Aviation Organization standards and recommendations for ground-proximity warning system (GPWS) equipment that provides predictive terrain-hazard warnings. “Enhanced GPWS (EGPWS)” and “ground collision avoidance system” are other terms used to describe TAWS equipment.

Source: Adapted from Carbaugh, David C. “Erroneous Flight Instrument Information.” In *Enhancing Safety in the 21st Century: Proceedings of the 52nd Annual International Air Safety Seminar*. Alexandria, Virginia, U.S.: Flight Safety Foundation, 1999.

Table 2
Unreliable Information/Systems With Pitot-static System Malfunction

System/Indicator	Notes
Autopilot	
Autothrottles	
Airspeed	
Altimeter	Blocked static system or blocked pitot-static system
Vertical speed	
Wind information	
Vertical navigation	
Terrain awareness and warning system*	Initial versions of terrain awareness and warning systems
Overspeed warning	
Wind shear warning	
Elevator feel	
Engine indication and crew alerting system messages	May not identify the basic problem

* Terrain awareness and warning system (TAWS) is the term used by the European Joint Aviation Authorities and the U.S. Federal Aviation Administration to describe equipment meeting International Civil Aviation Organization standards and recommendations for ground-proximity warning system (GPWS) equipment that provides predictive terrain-hazard warnings. "Enhanced GPWS (EGPWS)" and "ground collision avoidance system" are other terms used to describe TAWS equipment.

Source: Adapted from Carbaugh, David C. "Erroneous Flight Instrument Information." In *Enhancing Safety in the 21st Century: Proceedings of the 52nd Annual International Air Safety Seminar*. Alexandria, Virginia, U.S.: Flight Safety Foundation, 1999.

- "Keeping control of the airplane with basic pitch and power skills;
- "Taking inventory of reliable information;
- "Finding or maintaining favorable flying conditions;
- "Getting assistance from others; [and,]
- "Using checklists."

The most important action is maintaining "reasonable airplane control" with normal pitch and power settings, he said. "Troubleshooting should be done later."

In addition, he said, "Do not trust previously suspected instruments, even if they appear to be operating correctly again."

Michel Trémaud, senior director, safety and security, Airbus Customer Services, said, "Detecting an unreliable airspeed indication presents some traps: All indications may be consistent but equally

unreliable, [and] indications may differ, but attempting to assess the correct indication may be hazardous.⁸

"Abnormally large indicated-air-speed fluctuations are an obvious attention-getter [and] unusual differences between the captain's and first officer's instruments or between IAS and target airspeed may suggest an unreliable airspeed condition. ... Flight crew awareness of IAS/pitch/thrust/climb rate characteristics is the most effective clue; that is, IAS increasing with typical climb pitch attitude or IAS decreasing with typical descent pitch attitude would indicate a problem."

Other signs of unreliable airspeed indications include an unexpected stall warning, unexpected overspeed warning or simultaneous stall warning and overspeed warning; and an unanticipated IAS-aerodynamic noise relationship, Trémaud said.

If a flight crew detects an unreliable airspeed indication, typical procedures

call for achieving short-term flight path control with pitch and power and then conducting procedures discussed in the quick reference handbook for flight control through landing.

"The art and heart of this procedure is to achieve the desired speed by applying a given pitch attitude and a given power/thrust," Trémaud said. "This procedure is amazingly accurate in reaching the desired speed with a difference of less than five knots. However, applying this procedure with accuracy requires prior training in the simulator." (This type of simulator training is not included in type-qualification courses but may be included by operators in their recurrent training programs.)■

— FSF Editorial Staff

Notes

1. Carbaugh, David C. "Erroneous Flight Instrument Information." In *Enhancing Safety in the 21st Century: Proceedings of the 50th*

Annual International Air Safety Seminar. Alexandria, Virginia, U.S.: Flight Safety Foundation, 1999.

2. Commission of Accident Investigations, General Director of Air Transport, Peru. *Final Report: Accident of Boeing 757-200, Operated by an Airliner of Transport of Peru, South America, Aeroperu, Occurred on the Day of October 12, 1996*, [actual date was Oct. 2, 1996] *Location: Lima, Peru*. The original report was written in Spanish; an English translation was distributed by the Air Line Pilots Association, International.
3. FSF Editorial Staff. "Erroneous Airspeed Indications Cited in

Boeing 757 Control Loss." *Accident Prevention* Volume 56 (October 1999).

4. Carbaugh, David C. Interviews by Lacagnina, Mark, and Werfelman, Linda. Alexandria, Virginia, U.S., Oct. 24, 2004; Oct. 28, 2004. Flight Safety Foundation, Alexandria, Virginia, U.S. Additional information from Carbaugh, "Erroneous Flight Instrument Information."
5. Trémaud, Michel. E-mail communication with Werfelman, Linda. Alexandria, Virginia, U.S., Oct. 22–28, 2004. Flight Safety Foundation, Alexandria, Virginia, U.S.

6. Terrain-awareness and warning system (TAWS) is the term used by the European Joint Aviation Authorities and the U.S. Federal Aviation Administration to describe equipment meeting International Civil Aviation Organization standards and recommendations for ground-proximity warning system (GPWS) equipment that provides predictive terrain-hazard warnings; enhanced GPWS and ground collision avoidance system are other terms used to describe TAWS equipment.
7. Carbaugh. "Erroneous Flight Instrument Information."
8. Trémaud.

terrain display and predictive alerting functions leads to an earlier and improved detection rate of an altitude deviation resulting from altimetry-related anomalies;

- "The addition of a digital readout of geometric altitude on the terrain display leads to an earlier and improved detection rate of an altitude deviation resulting from altimetry-related anomalies; [and,]
- "Geometric altitude resulted in better and more consistent pilot decision making following the detection of an altitude anomaly — the display of geometric altitude does not negatively impact pilot decision making."

Ratan Khatwa, Ph.D., manager, flight safety human factors, Honeywell, said that minor differences are to be expected between the geometric-altitude display and the barometric altimeter indication. A significant difference during flight below transition altitude, however, could signal a problem. For example, the flight crew might have inadvertently mis-set the barometric altimeter; the QNH altimeter setting might be incorrect or the aircraft might be operating in an area of large differences from standard temperature or standard air pressure; or either the barometric altimeter or the static system might have failed.

Khatwa said that if a significant difference in the displays of geometric altitude and barometric altitude occurs in flight before the transition altitude, the flight crew should comply with the following procedures:

- "Check and confirm all altimeter settings;
- "Cross-check that any other barometric altimeters in the flight deck are in agreement;
- "Check that all altimeter settings are current and referenced to the landing airport;
- "Request assistance from ATC as necessary;
- "Monitor for significant temperature differences, especially in cold air. Updated weather information should be requested if in doubt; [and,]
- "Ensure that static ports are not iced over or are not partially blocked, and [that] heaters are switched on when below freezing."

The Honeywell study assigned the 30 participating pilots — all with about 8,000 flight hours to 9,000 flight hours and experience in using EGPWS — to one of three groups and presented them with several flight scenarios during a simulator session that was designed to evaluate their responses. Of the

Increased
use of geometric
altitude is
likely.

group of pilots who used a geometric-altitude display and a digital readout of geometric altitude, 97 percent positively detected altitude deviations. Of the group that used a display based on geometric altitude without a geometric-altitude readout, 78 percent detected altitude deviations. Of the group that used a display referenced only to barometric altitude, 49 percent detected the anomalies.

Evaluations of the pilots' responses to the flight scenarios found that 98 percent of those who used the geometric-altitude display and readout and 96 percent of those who used the geometric-altitude display responded correctly, compared with 78 percent of those who used only barometric altitude.

Pilots from all groups described their confidence level as "high, with respect to their ability to detect any altitude anomalies and their subsequent decision making," Khatwa said. Nevertheless, pilots using barometric altitude "often failed to detect altitude anomalies, and therefore, in those cases, [their] perceived terrain awareness did not match actual terrain awareness," he said.

Increased use of geometric altitude is likely, although geometric altitude is unlikely to replace barometric altitude in the near future.

"Use of EGPWS geometric altitude would eliminate the consequences of an incorrect altimeter setting or the consequences of not correcting the indicated altitude for extreme low outside air temperatures," said Michel Trémaud, senior director of safety and security for Airbus Customer Services.⁵²

Carbaugh said that increased reliance on geometric altitude computed from satellite data might be a distant goal.

"Pitot tubes and static ports are pretty old technology, prone to insect nests and other things that can mess them up," he said. "But satellite-based data, geometric altitude, would be a whole different world."

Bateman said that increased use of geometric altitude technology could eliminate many of the

problems connected with pressure altimeters. Nevertheless, he said, "I don't know how we could get by without pressure altimeters, as that is how the world of aviation flies today, with its QNE/QFE/QNH altimeter-setting references, ATC procedures and practices.

"If we could get rid of pressure altimetry and rely on [GPS-based geometric altitude], we could get rid of the possibility of false altimeter readings and common mode errors where the pressure altimeter can hurt the integrity of the flight. However, I believe we cannot guarantee the integrity of GPS everywhere in the world when we have inadvertent interference, or deliberate interference, nor could the United States probably ever get the rest of the world to switch over [to full reliance on GPS-based geometric altitude]."

In recent years, aircraft altimeters and other altitude-measuring devices have become very precise. Nevertheless, false indications still occur. Continuing research into new methods of altitude-measurement and new uses of existing technologies — such as radio altimeters and GPS-based geometric altitude — may lead to continued improvements in the accuracy of altitude-measuring systems. ■

Notes

1. International Civil Aviation Organization (ICAO). *Manual on Implementation of a 300 m (1,000 ft) Vertical Separation Minimum Between FL290 and FL410 Inclusive*. Document 9574. Second edition — 2002.
2. Ibid.
3. Joint Aviation Authorities (JAA). *Guidance Material on the Approval of Aircraft and Operators for Flight in Airspace Above Flight Level 290 Where a 300-meter (1,000-foot) Vertical Separation Minimum Is Applied*. Leaflet no. 6, Revision 1. Jan. 10, 1999.
4. U.S. Federal Aviation Administration (FAA). *Guidance Material on the Approval of Operations/Aircraft for RVSM Operations*. Document No. 91-RVSM. Feb. 20, 2004.
5. U.K. Civil Aviation Authority (CAA) Safety Regulation Group. *Flight Operations Department Communication 7/2004*. April 28, 2004.
6. Sanders, David. E-mail communication with Werfelman, Linda. Alexandria, Virginia, U.S., Nov. 1, 2004; Nov. 5, 2004. Flight Safety Foundation,

- Alexandria, Virginia, U.S. Sanders, a U.K. CAA press officer, said that the investigation is likely to continue for an “extended period.”
7. Honeywell. *Air Transport Avionics*. <www.cas.Honeywell.com/ats/products/nav.cfm>. Nov. 5, 2004.
 8. Carbaugh, David C. “Erroneous Flight Instrument Information.” *Boeing Aero* No. 23 (July 2003).
 9. Flight Safety Foundation (FSF) Controlled-flight-into-terrain (CFIT) Task Force. *CFIT Education and Training Aid*. 1996.
 10. CFIT, as defined by the FSF CFIT Task Force, occurs when an airworthy aircraft under the control of the flight crew is flown unintentionally into terrain, obstacles or water, usually with no prior awareness by the crew. This type of accident can occur during most phases of flight, but CFIT is more common during the approach-and-landing phase, which begins when an airworthy aircraft under the control of the flight crew descends below 5,000 feet above ground level (AGL) with the intention to conduct an approach and ends when the landing is complete or the flight crew flies the aircraft above 5,000 feet AGL en route to another airport.
 11. ICAO. Procedures for Air Navigation Services (PANS). *Aircraft Operations*, Volume 1: *Flight Procedures*. Part VI, *Altitude Setting Procedures*.
 12. Carbaugh, David C. Interview with Lacagnina, Mark, and Werfelman, Linda. Alexandria, Virginia, U.S., Oct. 28, 2004. Flight Safety Foundation, Alexandria, Virginia, U.S.
 13. U.K. CAA Level Bust Working Group. *On the Level Project Final Report*, Civil Aviation Publication 710. London, England. December 2000.
 14. European Organisation for Safety of Air Navigation (Eurocontrol). “Level Bust Briefing Notes: General.” June 2004. This is one of 14 briefing notes — related papers about level-bust issues — that are part of the European Air Traffic Management *Level Bust Toolkit*, a package of informational materials produced by Eurocontrol and designed to raise awareness of the level bust issue among aircraft operators and air navigation service providers and to help them develop strategies to reduce level busts.
 15. Law, John. “ACAS Provides an Effective Safety Net When Procedures Are Followed.” *Flight Safety Digest* Volume 23 (March 2004).
 16. Blajev, Tzvetomir. E-mail communication with Werfelman, Linda. Alexandria, Virginia, U.S., Nov. 5, 2004. Flight Safety Foundation, Alexandria, Virginia, U.S.
 17. Bateman, C. Donald. Telephone interview and e-mail communication with Werfelman, Linda. Alexandria, Virginia, U.S., Oct. 26, 2004; Oct. 29, 2004. Flight Safety Foundation, Alexandria, Virginia, U.S.
 18. FSF. “ALAR (Approach-and-landing Accident Reduction) Briefing Notes.” (“ALAR Briefing Note 3.1 — Barometric Altimeter and Radio Altimeter.”) *Flight Safety Digest* Volume 19 (August–November 2000).

The “ALAR Briefing Notes” are part of the *ALAR Tool Kit*, which provides on compact disc (CD) a unique set of pilot briefing notes, videos, presentations, risk-awareness checklists and other tools designed to help prevent approach-and-landing accidents (ALAs) and CFIT. The tool kit is the culmination of the Foundation-led efforts of more than 300 safety specialists worldwide to identify the causes of ALAs and CFIT, and to develop practical recommendations for prevention of these accidents. The tool kit is a compilation of work that was begun in 1996 by an international group of aviation industry volunteers who comprised the FSF ALAR Task Force, which launched the second phase of work begun in 1992 by the FSF CFIT Task Force.
 19. Hectopascal is the air-pressure measurement recommended by ICAO. The term is derived from the name of 17th-century French mathematician Blaise Pascal, who developed a method of measuring barometric pressure, and the Greek word for 100. One hectopascal is the equivalent of 100 pascals, or one millibar. One inch of mercury is equivalent to 33.86 hectopascals.
 20. FSF News Release: “Flight Safety Foundation Campaign to Reduce Controlled-flight-into-terrain Accidents Produces Safety Checklist, Specific Prevention Recommendations.” Nov. 2, 1994.
 21. FSF. “ALAR Briefing Notes.”
 22. The U.S. National Aeronautics and Space Administration (NASA) Aviation Safety Reporting System (ASRS) is a confidential incident-reporting system. The ASRS Program Overview said, “Pilots, air traffic controllers, flight attendants, mechanics, ground personnel and others involved in aviation operations submit reports to the ASRS when they are involved in, or observe, an incident or situation in which aviation safety was compromised.” ASRS acknowledges that its data have certain limitations. ASRS *Directline* (December 1998) said, “Reporters to ASRS may introduce biases that result from a greater tendency to report serious events than minor ones; from organizational and geographic influences; and from many other factors. All of these potential influences reduce the confidence that can be attached to statistical findings based on ASRS data. However, the proportions of consistently reported incidents to ASRS, such as altitude deviations, have been remarkably stable over many years. Therefore, users of ASRS may presume that incident reports drawn from a time interval of several or more years will reflect patterns that are broadly representative of the total universe of aviation safety incidents of that type.”
 23. NASA ASRS. Report no. 295007. January 1995.
 24. Thomas, Perry. “International Altimetry.” *ASRS Directline* No. 2 (October 1991).
 25. Patten, Marcia; Arri, Ed. “The Low-Down on Altimeter Settings.” *ASRS Directline* No. 9 (March 1997).
 26. NASA ASRS. Report no. 206218. March 1992.
 27. NASA ASRS. Report no. 289818. November 1994.
 28. NASA ASRS. Report no. 290122. December 1994.
 29. NASA ASRS. Report no. 295619. February 1995.
 30. The “sterile cockpit rule” refers to U.S. Federal Aviation Regulations Part 121.542, which states, “No flight crew-member may engage in, nor may any

- pilot-in-command permit, any activity during a critical phase of flight which could distract any flight crewmember from the performance of his or her duties or which could interfere with the proper conduct of those duties. Activities such as eating meals, engaging in nonessential conversations within the cockpit and nonessential communications between the cabin and cockpit crews, and reading publications not related to the proper conduct of the flight are not required for the safe operation of the aircraft. For the purposes of this section, critical phases of flight include all ground operations involving taxi, takeoff and landing, and all other flight operations below 10,000 feet, except cruise flight.” [The FSF ALAR Task Force says that “10,000 feet” should be height above ground level during flight operations over high terrain.]
31. FSF. “ALAR Briefing Notes.”
 32. Ibid.
 33. Thomas.
 34. NASA ASRS. Report no. 290848. December 1994.
 35. Patten, Arri.
 36. NASA ASRS. Report no. 292949. January 1995.
 37. NASA ASRS. Report no. 195014. November 1991
 38. NASA ASRS. Report no. 293372. January 1995.
 39. FSF. News Release: “Flight Safety Foundation Campaign to Reduce Controlled-flight-into-terrain Accidents Produces Safety Checklist, Specific Prevention Recommendations.” Nov. 2, 1994.
 40. FSF. News Release: “Recommendations Bring Safety Improvements.” Oct. 28, 2004.
 41. Airclaims. *Major Loss Record*. Volume 2 (Issue 139): ANZ:34.
 42. NASA ASRS. Report no. 566552. November 2002.
 43. U.S. National Transportation Safety Board. *Collision With Trees on Final Approach, American Airlines Flight 1572, McDonnell Douglas MD-83, N566AA, East Granby, Connecticut, November 12, 1995*. NTSB/AAR-96/05. November 1996.
 44. NASA ASRS. Report no. 190851. October 1991.
 45. Patten, Arri.
 46. ICAO. PANS. *Aircraft Operations*, Volume I: *Flight Procedures*. Part VI, *Altimeter Setting Procedures*.
 47. The Boeing Co. *Flight Crew Training Manual: 737-300/400/500*. 1999.
 48. Wilkes, Jack. “Cold and Low, Look Out Below.” *Air Line Pilot* Volume 68 (January 1999).
 49. Terrain awareness and warning system (TAWS) is the term used by JAA and FAA to describe equipment meeting the ICAO standards and recommendations for ground-proximity warning system (GPWS) equipment that provides predictive terrain-hazard warnings. “Enhanced GPWS (EGPWS)” and “ground collision avoidance system” are other terms used to describe TAWS equipment.
 50. Harris, David. *Ground Studies for Pilots: Flight Instruments and Automatic Flight Control Systems*. Oxford, England: Blackwell Science, 2004.
 51. Khatwa, Ratan. “Human Factors Evaluation of Vertical Situational Awareness: Altimetry Errors.” In *Safety Without Borders, Proceedings of the 16th Annual European Aviation Safety Seminar*. Alexandria, Virginia, U.S.: Flight Safety Foundation, 2004.
 52. Trémaud, Michel. E-mail communication with Werfelman, Linda. Alexandria, Virginia, U.S., Oct. 24–Oct 28, 2004. Flight Safety Foundation, Alexandria, Virginia, U.S.
 - FSF Editorial Staff. “Faulty Shift Handoff Cited in Failure to Close B-747 Static Lines.” *Aviation Mechanics Bulletin* Volume 52 (January–February 2004).
 - FSF Editorial Staff. “ALAR (Approach-and-landing Accident Reduction) Briefing Notes.” *Flight Safety Digest* Volume 19 (August–November 2000).
 - FSF Editorial Staff. “Erroneous Airspeed Indications Cited in Boeing 757 Control Loss.” *Accident Prevention* Volume 56 (October 1999).
 - U.S. National Transportation Safety Board. “Controlled Flight Into Terrain: Korean Air Flight 801, Boeing 747-300, HL7468, Nimitz Hill, Guam, August 6, 1997.” *Flight Safety Digest* Volume 19 (May–July 2000).
 - Flight Safety Foundation Approach-and-landing Accident Reduction Task Force. “Killers in Aviation: FSF Task Force Presents Facts About Approach-and-landing and Controlled-flight-into-terrain Accidents.” *Flight Safety Digest* Volumes 17–18 (November 1998–February 1999).
 - FSF Editorial Staff. “During Nonprecision Approach at Night, MD-83 Descends Below Minimum Descent Altitude and Contacts Trees, Resulting in Engine Flame-out and Touchdown Short of Runway.” *Accident Prevention* Volume 54 (April 1997).
 - FSF Editorial Staff. “Learjet MEDEVAC Flight Ends in Controlled-flight-into-terrain (CFIT) Accident.” *Accident Prevention* Volume 54 (January 1997).
 - Khatwa, R.; Roelen, A.L.C. “An Analysis of Controlled-flight-into-terrain (CFIT) Accidents of Commercial Operators, 1988 Through 1994.” *Flight Safety Digest* Volume 15 (April–May 1996).
 - Sumwalt, Robert L. III. “Altitude Awareness Programs Can Reduce Altitude Deviations.” *Flight Safety Digest* Volume 14 (December 1995).
 - FSF Editorial Staff. “Rejected Takeoff in icy Conditions Results in Runway Overrun.” *Accident Prevention* Volume 52 (May 1995).
 - Pope, John A. “Research Identifies Common Errors Behind Altitude Deviations.” *Flight Safety Digest* Volume 12 (June 1993).

Further Reading From FSF Publications

FSF Editorial Staff. “System Flags Altimeter-setting Errors in Weather Observations.” *Airport Operations* Volume 30 (September–October 2004).

U.S. Hazardous-materials Incidents In Aviation Were Rarely Fatal

From 1994 through 2003, only the 1996 ValuJet accident resulted in fatalities during the transportation of hazardous materials by aircraft. Injuries in this incident category averaged about 20 per year.

— FSF EDITORIAL STAFF

The 751 U.S. hazardous-materials incidents¹ in aviation reported in 2003 to the U.S. Department of Transportation (DOT) resulted in damages totaling more than US\$100,000. One minor injury occurred in those incidents (Table 1). This was the lowest number in a pattern of declining annual total injuries for the period 1994–2003 (Table 2, page 24). There was a total of 10,657 hazardous-materials aviation incidents (an average of 1,065.7 per year), but in all years except 1996 no fatalities resulted. The 10-year total of major injuries or minor injuries² was 202 (an average of 20.2 per year). Reported incidents, injuries and damages in 2002 and 2003 were below the corresponding averages for the 10-year period.

A hazardous material is defined in U.S. regulations³ as “a substance or material that the Secretary of Transportation has determined is capable of posing an unreasonable risk to health, safety and property when transported in commerce.”

Analysis of hazardous-materials aviation incidents reported in 2003 (Table 1) showed that 662 incidents (88 percent) were attributed to human error and 86 incidents (11 percent) were attributed to package failure.

Based on the current definition of a hazardous-materials aviation serious incident, the 13 that occurred in 2003 were lower than the 10-year average of 17.1 and lower than the numbers in each of the

previous five years (Table 3, page 24). There were no fatalities in serious incidents in 2003, and none have occurred since the May 11, 1996, accident involving a ValuJet McDonnell Douglas DC-9. [The aircraft had just departed from Miami (Florida, U.S.) International Airport when an intense fire erupted in the forward cargo compartment. While the flight crew attempted to turn back to the airport, the fire burned through the control cables, control was lost and the aircraft struck

Table 1
U.S. Hazardous-materials Incidents in Aviation, by Cause, 2003

Cause	Incidents	Injuries		Fatalities	Damages (US\$)*
		Major	Minor		
Human Error	662	0	1	0	90,257
Package Failure	86	0	0	0	5,495
Vehicular Accident	0	0	0	0	0
Other	3	0	0	0	4,731
Total	751	0	1	0	100,483

*Damages include the estimated U.S. dollar cost of product loss, property damage, and decontamination or clean-up.

Source: U.S. Department of Transportation Hazardous Materials Information System

Table 2
U.S. Hazardous-materials Incidents in Aviation, 1994–2003

	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	Total
Incidents	931	817	925	1,031	1,386	1,582	1,419	1,083	732	751	10,657
Fatalities	0	0	110	0	0	0	0	0	0	0	110
Injuries	57	33	33	24	20	12	5	13	4	1	202
Damages (US\$)*	177,695	100,431	87,188	336,178	266,628	286,104	271,629	309,189	108,630	100,483	2,044,155

*Damages include the estimated U.S. dollar cost of product loss, property damage, and decontamination or clean-up.

Source: U.S. Department of Transportation Hazardous Materials Information System

Table 3
U.S. Hazardous-materials Serious Incidents in Aviation, 1994–2003

	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	Total
No. of Incidents	14*/7**	10/8	11/6	11/13	23/22	12/16	11/35	10/36	5/15	8/13	115/171
No. of Fatalities	0/0	0/0	110/110	0/0	0/0	0/0	0/0	0/0	0/0	0/0	110/110
No. of Injuries	33/21	22/12	15/1	4/1	4/4	4/0	0/0	3/6	0/0	0/0	85/45
Damages (US\$)***	69,871/ 70,272	4,750/ 1,805	11,390/ 0	6,209/ 2,651	26,168/ 22,429	6,187/ 7,405	49,059/ 53,931	68,034/ 27,529	60,475/ 12,000	1,825/ 1,715	303,968/ 199,737

*The U.S. Department of Transportation (DOT) revised the definition of a serious incident in 2002. The figure to the left of each slash uses the previous definition:

- A fatality or major injury caused by the release of a hazardous material;
- A closure of a major transportation artery;
- The evacuation of six or more persons due to the presence of a hazardous material; or,
- A vehicle accident or derailment resulting in the release of a hazardous material.

**DOT revised the definition of a serious incident in 2002. The figure to the right of each slash uses the current definition:

- A fatality or major injury caused by the release of a hazardous material;
- The evacuation of 25 or more persons as a result of release of a hazardous material or exposure to fire;
- A release or exposure to fire which results in the closure of a major transportation artery;
- The alteration of an aircraft flight plan or operation;
- The release of radioactive materials from Type B packaging;¹
- The suspected release of a Risk Group 3 or Risk Group 4 infectious substance;²
- The release of more than 11.9 U.S. gallons (45 liters) or 88.2 pounds (40 kilograms) of a severe marine pollutant; or,
- The release of a bulk quantity (more than 119 U.S. gallons [450 liters] or 882 pounds [400 kilograms]) of a hazardous material).

¹Type B packaging is designed to retain the integrity of its containment and shielding when subjected to the normal conditions of transport and specified accident-test conditions.

²Risk groups, which rank a micro-organism’s ability to cause injury through disease, are defined in 49 U.S. Code of Federal Regulations 173.134, Class 6, Division 6.2 — *Definitions and exceptions*.

***Damages include the estimated U.S. dollar cost of product loss, property damage, and decontamination or clean-up.

Source: U.S. Department of Transportation Hazardous Materials Information System

terrain. All 110 occupants were killed. The U.S. National Transportation Safety Board (NTSB) said that the fire resulted from the improper carriage of oxygen generators as cargo, and determined as one of the accident’s three probable causes “the failure of ValuJet to properly oversee its contract maintenance program to ensure compliance with maintenance,

maintenance-training and hazardous-materials requirements and practices.”]

No injuries were reported in U.S. hazardous-materials aviation serious incidents in 2003, compared with an annual average of five in the previous nine years. The annual total damage⁴ resulting from serious incidents in the

1994–2003 period varied significantly year to year and from the beginning to the end of the period.

For the first time in the 10-year period, there were no hazardous-material aviation incidents involving radioactive materials in 2003 (Table 4, page 25). Such incidents had averaged 4.7

Table 4
U.S. Hazardous-materials Incidents in Aviation, Radioactive Materials, 1994–2003

	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	Total
Incidents	4	3	8	3	3	5	7	6	3	0	42
Fatalities	0	0	0	0	0	0	0	0	0	0	0
Injuries	0	0	0	0	0	0	0	0	0	0	0
Damages (US\$)*	0	50	1,500	1,853	685	0	0	0	12,000	0	16,088

*Damages include the estimated U.S. dollar cost of product loss, property damage and decontamination or clean-up.

Source: U.S. Department of Transportation Hazardous Materials Information System

annually in the previous nine years. There were no fatalities or injuries involving radioactive materials during the 10-year period, and the annual variation in damage showed no discernible trend.

Incidents involving hazardous waste⁵ (Table 5) totaled 10 in the period,

with one reported in 2003, the same as the annual average for the period. There were no fatalities or injuries, and the annual totals for damage varied significantly.

In 2003, Tennessee was the state with the most reported hazardous-materials aviation incidents (265), followed

by Ohio (114), Kentucky (70) and California (43). ■

[This article is based on data published by the U.S. Department of Transportation Hazardous Materials Information System, available on the Internet at <hazmat.dot.gov/files/hazmat/hmisframe.htm>.]

Table 5
U.S. Hazardous-materials Incidents in Aviation, Hazardous Waste, 1994–2003

	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	Total
Incidents	1	0	0	2	2	2	1	1	0	1	10
Fatalities	0	0	0	0	0	0	0	0	0	0	0
Injuries	0	0	0	0	2	0	0	1	0	0	3
Damages (US\$)*	0	0	0	75	5,075	2,000	0	0	0	0	7,150

*Damages include the estimated U.S. dollar cost of product loss, property damage and decontamination or clean-up.

Source: U.S. Department of Transportation Hazardous Materials Information System

Notes

1. A hazardous-materials incident involves any of the following conditions specified in 49 U.S. Code of Federal Regulations (CFR) 171.15, *Immediate notice of certain hazardous materials incidents*, and 171.16, *Detailed hazardous materials incident reports*:

- A person is killed or hospitalized;
- Estimated carrier and/or property damage exceeds US\$50,000;
- Evacuation of the general public occurs, lasting one or more hours;
- One or more major transportation arteries or facilities are closed or shut down for one hour or more;
- The operational flight plan or routine of an aircraft is altered;

- Fire, breakage, spillage or suspected radioactive contamination occurs involving the shipment of etiological agents [viable micro-organisms or their toxins that can cause human disease];
- There is any unintentional release of a hazardous material during transportation (including loading, unloading and temporary storage related to transportation); or,
- The carrier judges that the situation should be reported even though it does not meet the criteria.

The carrier experiencing a hazardous-materials incident must file an incident report with the U.S. Department of Transportation (DOT). The regulations make no distinction between U.S.-registered and non-U.S.-registered carriers. Incident reports are the source of

the data on hazardous-materials aviation incidents.

2. A major injury is an injury that requires hospitalization or results in time lost from work. Michelle Glode, Catapult Technology, contractor to DOT. E-mail communication with Darby, Rick. Alexandria, Virginia, U.S. Oct. 20, 2004. Flight Safety Foundation, Alexandria, Virginia, U.S.
3. 49 CFR 105.5, *Definitions*.
4. *Damage* includes the estimated U.S. dollar cost of product loss, property damage and decontamination or clean-up.
5. *Hazardous waste* is defined in 49 CFR 172.101, *Purpose and use of hazardous materials table*, as “any material that is subject to the hazardous-waste manifest requirements of the U.S. Environmental Protection Agency specified in 40 CFR Part 262 [*Standards applicable to generators of hazardous waste*].”

Entropy Model of Accident Causation Proposed

Looking at organizational accident-risk factors in terms of the degradation of system factors is more effective than the human-error model, says an environmental health specialist.

— FSF LIBRARY STAFF



Books

Productive Safety Management: A Strategic, Multi-disciplinary Management System for Hazardous Industries That Ties Safety and Production Together. Mol, Tania. Oxford, England: Butterworth-Heinemann, 2003. 435 pp. Figures, tables, references, glossary, index.

“The theoretical models that explain how accidents happen have been used to underpin current OHS [occupational health and safety] management systems,” says the author. “These models have strongly emphasized the role of human error as a major contributing factor in safety deviations. They contain references to ‘unsafe acts,’ ‘mental condition of [the] worker,’ ‘physical condition of [the] worker,’ ‘perceptual skills’ and other individual-centered terms. As a result, it has become easy to blame the worker when something goes wrong.”

But this approach to accident reduction, says the author — a human resource manager and environmental health officer in Australia — is of limited effectiveness. Workers do not need to be convinced that they are better off not being injured

at work. Few workers knowingly act recklessly. Instead, she says, “they tend to behave according to the demands of the organizational system and its culture.” In other words, workers take risks not out of ignorance or indifference, but from a desire to fit in with a company’s accepted norms and to meet its expectations.

To replace the human-error model of accident causation, the author proposes the entropy model. Entropy, in this context, means the degradation of an organization’s system factors — processes, technology, the physical environment and human resources. “Systemic weaknesses such as inadequate training, production pressures, excessively demanding tasks, high-risk environments, faulty equipment and long work hours contribute to accidents,” says the author. “These are, in large measure, not matters directly controlled by the worker. The entropy model provides a balanced perspective of these contributing variables and explains how risks associated with system factors can be managed effectively.”

A second tool for safety management is included in what the author calls the “strategic alignment channel,” which challenges the concept of

management making decisions that flow in a single “stream” from the top levels to the bottom levels of the firm. The strategic alignment channel she recommends consists of three streams: external strategic alignment, which aligns organizational goals and values with the external environment; internal strategic environment, which aligns human capital, physical capital and financial capital; and internal goal alignment, which aligns organizational goals and values with employees’ goals and values. According to this theory, when internal goal alignment is absent, the operational level can be a conflict zone with supervisors caught in the middle trying to balance the divergent goals of management and subordinates.

“Internal goal alignment ensures that safety systems and practices encourage employee participation, high levels of vigilance and behaviors that shift system factors towards optimal safety, performance and quality,” the author says.

The book is written for managers and supervisors working in hazardous industries, engineers, academia and management professionals. Nevertheless, readers may draw parallels across industries regarding risk reduction and risk control; safety systems development; safety cultures; workplace competencies; legal responsibilities; and social responsibilities.

Instrument Procedures Handbook. Oklahoma City, Oklahoma, U.S.: U.S. Federal Aviation Administration (FAA) Flight Procedure Standards Branch. 248 pp. Figures, appendixes, index. Available from GPO.*

The *Instrument Procedures Handbook* is a technical reference for pilots who conduct instrument flight rules (IFR) operations in the U.S. national airspace system. The book also can serve as a training aid, providing detailed information about instrument charts and procedures, including takeoff, departure, en route, arrival, approach and landing phases of flight.

Safety-related information is woven throughout the text. Among the subjects discussed from a risk-reduction standpoint are runway incursions, land-and-hold-short operations (LAHSO), controlled flight into terrain (CFIT) and human factors.

Color illustrations and reproductions of instrument charts with certain features emphasized by yellow highlighting or red borders help the reader comprehend details discussed in the text.


In addition to chapters about instrument procedures during the various phases of flight, the book has chapters about the U.S. national airspace system and about system-improvement plans. Appendixes discuss airborne navigation databases, approach-chart format changes and helicopter instrument procedures. A final appendix is devoted to acronyms and a glossary.

Flying High. Wynbrandt, James. Hoboken, New Jersey, U.S.: John Wiley & Sons, 2004. 298 pp. Notes, index.

Following its first scheduled flight on Feb. 11, 2000, JetBlue showed how a contemporary start-up airline could become popular and profitable in a relatively short time. *Flying High* is a biography of its founder and CEO, David Neeleman, who the author says is “arguably the most innovative figure in modern-day aviation.” The book is also a study of the business model and management principles that the company has followed.

Neeleman, who as president of Morris Air turned the former charter operator into a profitable scheduled airline, was influenced by the management principles of Southwest Airlines, to which he eventually sold Morris Air. When he decided to create an airline, the author says, he “pledged to bring ‘humanity’ back to air travel, with a fleet of brand-new aircraft fitted with leather seats and individual live television that passengers could watch throughout the entire flight. What’s more, he insisted that JetBlue would be customer-focused, while offering fares that would be about two-thirds lower than what the competition had previously charged. He further promised that his company would demonstrate the right way to treat customers and employees, deliver service in an industry that had forgotten the meaning of the word, use technology to streamline operations and cut costs in a way that would yield a competitive advantage.”

Ordering an all-new fleet (Airbus A320s) was an unprecedented step for a start-up airline. Cost analysis had convinced Neeleman that the money saved by buying used aircraft would be more than negated by the higher maintenance cost of an older



fleet. He also believed that passengers prefer new aircraft.

Other JetBlue innovations included being the first airline to use electronic ticketing, or “e-ticketing,” exclusively and having reservation agents work from their homes, thus eliminating the cost of maintaining a call center. The airline worked with the U.S. Federal Aviation Administration (FAA) to complete the certification process that made possible a “paperless cockpit,” in which the aircraft flight manual is electronic, accessed by the pilots’ laptop computers. The computers also enable the pilots to perform weight-and-balance calculations, fuel calculations and other flight-planning tasks that are conventionally handled by dispatchers, saving time and avoiding the cost of having a large flight-dispatch department.

Choosing to base the airline at John F. Kennedy International Airport (JFK), New York, N.Y., U.S., went against the conventional wisdom that JFK was disliked by travelers because it was perceived as overcrowded and too distant from Manhattan, New York’s business and cultural center. But Neeleman found that there were five million people living closer to JFK than to New York’s other two major airports. “As for airport congestion, an examination of operations revealed that JFK was only busy in the evening when transatlantic flights stacked up to depart for overnight flights to Europe,” the author says. “For most of the day, the airport was actually underutilized.”

JetBlue’s employment practices are also unusual, designed to create and maintain an *esprit de corps* that leads to high-quality customer relations. In its own terminology, the airline has no employees — they are all “crewmembers.” The primary job qualification to work for JetBlue, says the author, “is that prospective crewmembers must like people. ... Company recruiters look for signs of the fun-loving, team-oriented spirit its crewmembers are known for, as well as behaviors that mirror the values JetBlue is built on.” Pilot applicants who pass the initial screening often meet with senior company executives, including Neeleman. JetBlue also pays its trainees (flight attendants as well as pilots) during initial training.

The book concludes with Neeleman’s “rules for succeeding in any business.”

Reports

Simulated Evacuations Into Water. McLean, G.A.; Palmerton, D.A.; Corbett, C.L.; Larcher, K.G.; McDown, J.R. U.S. Federal Aviation Administration (FAA) Office of Aerospace Medicine (OAM). DOT/FAA/AM-04/12. August 2004. 8 pp. Table, figures, references. Available on the Internet at <www.cami.jcccbi.gov> or through NTIS.**

Under U.S. Federal Aviation Regulations (FARs) Part 25.801, *Ditching*, “it must be shown that, under reasonably probable water conditions, the flotation time and trim of the [transport category] airplane will allow the occupants to leave the airplane and enter the life rafts required by [FARs Part] 25.1415 (1).” The planned designs of very large transport airplanes with two passenger decks have called into question the assumptions made in previous tests of passenger egress into water, because lower-deck exit sills in these new types could require passengers to jump from heights as much as six feet [two meters] above the water. “This may create significant deviations from the passenger-flow rates into the water [that were] assumed historically for transport airplanes, especially those caused in part by the speed with which passengers can vacate the area immediately adjacent to the aircraft exit once they have entered the water,” says the report.

To provide data relative to such certification questions, the FAA Civil Aerospace Medical Institute (CAMI) conducted a study using its water-survival research tank to evaluate simulated evacuation under varied conditions. Participants jumped from a platform into water at heights ranging from 0.75 foot (0.23 meter) to six feet. They were instructed that they must not jump on top of any of their fellow participants already in the water.

The effects of three different flotation-device conditions also were investigated. Participants jumped into the water (1) while holding typical transport category airplane flotation seat cushions; (2) while wearing a technical standard order (TSO)-approved inflatable life vest that was already inflated; and (3) while wearing a TSO-approved life vest that was uninflated, with the participant inflating it after entering the water.

The effects of platform height were statistically significant, with egress times increasing by an average

0.7 second per person as the height of the platform was increased from 0.75 foot to six feet. “Such effects can be related to the fear generally associated with jumping from high places, although the instruction that participants were given about being sure not to jump onto another person already in the water also appeared to play a part,” says the report.

The experimenters also found that the flotation-device type affected individual egress time. “Flotation seat cushions [produced] the lowest flow rates, followed next by life vests that were uninflated until entry into the water and then life vests that had been inflated before leaving the platform,” says the report.

The differences in egress time associated with various flotation-device types appeared to reflect both the difficulty some participants had in moving away from the tank’s landing area and the time they spent under water after jumping, the report says.

“The lack of inflation upon entering the water with the uninflated life vest allowed participants to plunge much further into the water, increasing their underwater time in the landing area and ... resulted in added delays to participants on the platform who had to make sure the water was clear before jumping,” says the report.

The flotation seat cushion provided immediate flotation upon entering the water, but was found to make moving through the water difficult. “This occurred because the cushion formed somewhat of a barrier that had to be pushed through the water to move away from the landing area, and the participant’s arms had to be locked around the cushion, eliminating any ability to use them for swimming,” says the report.

The pre-inflated life vests offered the benefits of immediate flotation and of allowing participants full use of their arms to swim easily and move away from the landing area more quickly, the report says.

“The results presented here suggest that, in terms of escape and moving away from a ditched airplane, pre-inflation is a good idea,” says the report. “In mitigation of these findings are accident reports and personal accounts of crash survivors, which indicate that passengers have been [trapped] and

may become trapped inside the airplane should they inflate their [life] vests and the exits then sink below waterline. Given both arguments, it would appear that a well-chosen course of action would be to maintain the [life] vests in an uninflated condition until the passenger begins to jump from the airplane exit, pulling the inflation handles in midair to create life vest buoyancy before hitting the water.”

[For a detailed discussion of life vest use in water-contact accidents, see “Your Life Vest Can Save Your Life ... If It Doesn’t Kill You First,” in *Waterproof Flight Operations*, a special issue of *Flight Safety Digest*, September 2003–February 2004, available on compact disc from Flight Safety Foundation.]

Regulatory Materials

Hazardous Wildlife Attractants on or Near Airports. U.S. Federal Aviation Administration (FAA) Advisory Circular (AC) 150/5200-33A. July 27, 2004. Figures, tables, appendix, references. 18 pp. Available from FAA via the Internet at <http://www.airweb.faa.gov/Regulatory_and_Guidance_Library> or from GPO.*

The availability of information about risks posed to aircraft by certain wildlife species has increased significantly in recent years. Reporting and documentation of incidents have improved, as have formal studies and data collection. FAA says that these studies and data show that aircraft collisions with birds and other wildlife create serious economic problems and serious public safety problems. This AC says, “During the past century, wildlife-aircraft strikes have resulted in the loss of hundreds of lives worldwide, as well as billions of dollars in aircraft damage.”

Many species of wildlife can threaten aircraft safety. They are not equally hazardous, however. Table 1 in this AC ranks 25 species groups commonly involved in damaging strikes in the U.S. according to three criteria: aircraft damage, major aircraft damage and effect on flight. Listed in descending order according to a composite score based on all three criteria, with a maximum score of 100, the top 10 are deer (score: 100), vultures (64), geese (55), cormorants and pelicans (54), cranes (47), eagles (41), ducks (39), osprey (39), turkeys and pheasants

(33), and herons (27). Hazard rankings are based on 47,212 records in the FAA National Wildlife Strike Database for the years 1990 to 2003.

The AC contains numerous references to sources of additional information. The following documents are available in paper format or on the Internet:

- *Special Report for the FAA, Ranking the Hazard Level of Wildlife Species to Civil Aviation in the USA: Update 1, July 2, 2003* <<http://www.faa.gov>>;
- *Wildlife Hazard Management at Airports: A Manual for Airport Personnel*, prepared by FAA staff and the staff of the U.S. Department of Agriculture <<http://wildlife-mitigation.tc.faa.gov>>;
- *Prevention and Control of Wildlife Damage*, compiled by the University of Nebraska [U.S.] Cooperative Extension Division <<http://ianrwww.unl.edu/wildlife/solutions/handbook>>;
- *Construction or Establishment of Landfills Near Public Airports*, FAA AC 150/5200-34 <<http://www.faa.gov>>;
- *Airport Design*, FAA AC 150/5300-13 <<http://www.faa.gov>>; and,
- *Wildlife Control Procedures Manual*, Technical Publication 11500E, 1994, Transport Canada, Airports Group <<http://www.tc.gc.ca/CivilAviation/Aerodrome/WildlifeControl/tp11500/Introduction.htm>>.

AC 150/5200-33A provides guidance on use of land that could attract hazardous wildlife on or near airports. The FAA recommends implementation of the standards and practices contained in the AC by operators of certified public-use airports, operators of noncertified public-use airports, and developers of projects, facilities and activities on or near airports. Standards and practices addressed in the AC are:

- Separation criteria for hazardous wildlife attractants on or near airports;
- Land-use practices on or near airports that potentially attract hazardous wildlife;
- Procedures for wildlife hazard management by operators of public-use airports; and,

- FAA review of proposed land-use changes.

[This AC cancels AC 150/5200-33, *Hazardous Wildlife Attractants on or Near Airports*, dated May 1, 1997.]

Precision Approach Path Indicator (PAPI)

Systems. U.S. Federal Aviation Administration (FAA). Advisory Circular (AC) 150/5345-28E. May 25, 2004. 14 pp. Figures, references. Available on the Internet at <<http://www2.faa.gov/arp/150acs.cfm>> or from GPO.*

Precision approach path indicator (PAPI) systems provide pilots with visual glide path guidance during approach for landing. This AC contains FAA standards, specifications and requirements for PAPI systems and for equipment tests.

In addition to containing PAPI qualification requirements, this AC provides references to related FAA ACs, FAA standards and drawings, SAE International standards, Illuminating Engineering Society Transactions, and select U.S. Department of Defense military specifications and standards.

Three principal changes appear in this updated AC:

- The section "Siting and Installation Standards" has been moved to AC 150/5340-30, *Design and Installation Details for Airport Visual Aids*;
- A chromaticity [precise specification of color] test requirement has been added; and,
- An optional go/no go PAPI lamp-monitoring output function has been added.

[This AC cancels AC 150/5345-28D, *Precision Approach Path Indicator (PAPI) Systems*, dated May 23, 1985.] ■

Sources

- * U.S. Government Printing Office (GPO)
732 North Capitol St. NW
Washington, DC 20401 U.S.
- ** National Technical Information Service (NTIS)
5285 Port Royal Road
Springfield, VA 22161 U.S.
Internet: <www.ntis.gov>



Turbine Disk Fails During Departure

The accident report said that the uncontained engine failure resulted from fatigue cracks in an area damaged by shot-peening that had been performed either during the manufacture of the engine or during repairs.

— FSF EDITORIAL STAFF

The following information provides an awareness of problems through which such occurrences may be prevented in the future. Accident/incident briefs are based on preliminary information from government agencies, aviation organizations, press information and other sources. This information may not be entirely accurate.

disk.” Among components damaged by the uncontained debris was a leading-edge-flap panel above the no. 1 engine. Because of the damage, the flight crew did not use the leading-edge flaps during the return flight.

The report said that fatigue cracks had developed in the turbine disk in an area that had been damaged by shot-peening during manufacture or repair of the disk. (Shot-peening is a process in which metal shot is blasted against a metal part to strengthen it.)

“While subsequent fatigue testing of other [disks] with similar surface damage did not conclusively identify a loss of fatigue life resulting from the peening processes, it is known that overly heavy or abusive shot-peening can prove detrimental to fatigue performance,” the report said. “As a result of the findings of the investigation, the engine manufacturer has implemented several changes to the manufacturing and repair shot-peening processes, to avoid the surface damage found on the failed disk.”

The Australian Civil Aviation Safety Authority and the U.S. Federal Aviation Administration subsequently mandated the manufacturer’s changes to the shot-peening processes.

Some Cabin Crewmembers Not Told About Emergency Landing Plans

Boeing 767-200. Substantial damage. No injuries.

An uncontained failure of the no. 1 (left) engine occurred about six minutes after the airplane departed from an airport in Queensland, Australia, for a scheduled flight to New Zealand. The flight crew flew the airplane back to the departure airport and landed without further incident.

The accident report said that the failure of the General Electric CF6-80A turbofan engine resulted from “the fracture and liberation of a large segment from the first-stage high-pressure turbine

AIR CARRIER



The investigation also found that after the engine failed, there was a miscommunication of the flight crew's intention to prepare the passengers for an emergency landing.

"The flight crew's subsequent call for the 'brace' position at 500 feet thus came as a surprise to the unaware cabin crew, some of whom adopted the unprepared emergency landing procedures, calling 'emergency, grab your ankles' to the passengers," the report said. "The aircraft operator, as part of its own investigation into the occurrence, has developed a series of recommendations aimed at addressing the crew-communication deficiencies experienced ... after the engine failure."

Airplane Strikes Rudder of Aircraft on Intersecting Taxiway

Airbus A319. Minor damage. No injuries. Canadair CL-600 Challenger. Minor damage. No injuries.

While being taxied for takeoff at an airport in the United States, the Airbus A319 struck the Canadair CL-600, which was on a taxiway, holding short of an active runway.

The crews of both airplanes had received taxiing instructions to the same runway. The A319 captain said that, as he taxied his airplane, he observed the CL-600 on an intersecting taxiway and that he "felt confident there was adequate room to safely pass them." He said that when he was certain that his airplane had passed the CL-600's tail, he looked forward and "in approximately one second, we came to a stop. I looked left and saw our wing tip against the [CL-600's] rudder."

The CL-600 crew said that they were parked on the taxiway when they felt a "jolt" to their airplane.

Both airplanes were taxied back to the gate area.

Vehicle Strikes Airplane at Gate

Boeing 737. Minor damage. No injuries.

The crew was preparing for departure from an airport in Northern Ireland and had received clearances for push-back and start when

they heard and felt something strike the airplane. The flight crew interrupted the "cleared for start" checklist, and a member of the ground crew told the captain that a collision had occurred.

The captain left the airplane to investigate and observed that a vehicle that typically was used to move ground equipment within the apron (ramp) area had struck the airplane on the left side below the flight deck windows. He observed two "large penetrations" — 20 centimeters (66 inches) long and 30 centimeters (98 inches) long — in the airplane's outer skin, the report said.

The driver of the vehicle said that he inadvertently had placed his foot on the accelerator instead of the brake and that he was unable to stop the vehicle before its roof struck the fuselage.

"During his attempt to avoid the collision, the driver turned the steering wheel hard left; as a consequence, a lamp-cluster mounted on the nearside rear corner of the [vehicle's] roof struck the fuselage side as the vehicle came to rest, resulting in a second penetration of the fuselage skin," the report said.

Tug Strikes Radome During Tow


BAE Systems ATP. Substantial damage. No injuries.

After the aircraft was pushed back from the gate for departure from an airport in Ireland, the captain asked the ground-handling personnel to pull the aircraft forward to allow clearance for another aircraft that was being pushed back from an adjacent gate. As the ATP was being pulled forward, the tug's (tractor's) roof struck the aircraft's radome.

The aircraft manufacturer told investigators that the tow bar used in the ground operation was not approved for towing the ATP. The tow bar was 133.5 inches (339.1 centimeters) long; the approved custom-built tow bar for the ATP is 140.0 inches (355.6 centimeters) long.

The tow bar used in the ground operation had been supplied by the operator of the ATP. The operator also had recommended use of the tug, which was 6.0 feet (1.8 meters) tall.

AIR TAXI/COMMUTER



“With the tug and tow bar in use, it was possible for the tug to strike the radome when the front of the tug in use was at an angle of about 60 degrees to the centerline of the aircraft,” the accident report said. “This angle was probably never envisaged in operation, as it would have been considered excessive. ... A smaller, more maneuverable tug would have been more suitable [for the operation].”

The ground-handling personnel told investigators that they were apprehensive about towing the aircraft forward with its propellers turning.

“They acceded to the request of the captain in order to expedite the departure,” the report said.

After the accident, the ground-handling contractor issued a line-maintenance notice stating that “the only way the aircraft is to be towed forward is to request that the engines be shut down, [safety] pins installed and tug reversed to the tow position,” the report said.

Cabin-pressure Anomaly Prompts Emergency Descent

Fairchild SA227-DC Metro 23. No damage. No injuries.

The airplane was being flown at Flight Level 220 (approximately 22,000 feet) over Western Australia when the flight crew observed an indication that the cabin altitude was increasing at a rate of about 8,000 feet per minute.

“The crew, suspecting a pressurization [system] failure, donned oxygen masks and directed the passengers to do the same,” the incident report said.

The crew received clearance from air traffic control to conduct a descent to 14,000 feet.

“Once level at the amended cruise altitude, the use of passenger oxygen masks was discontinued, and the flight proceeded to Perth,” the report said. “Company maintenance investigation could not detect the reason for the pressurization fault. Extensive troubleshooting was carried out in accordance with the manufacturer’s maintenance manual, followed by ground runs and a test flight. The aircraft and its systems performed normally.

“The aircraft was placed on a maintenance watch and returned to service, where it has since [been] operated without incident.”

Landing Gear Collapses During Taxi

Piper PA-23-250E Aztec. Substantial damage. No injuries.

The airplane was being taxied to the fuel pumps at an airport in New Zealand after a domestic cargo flight. As the airplane slowed to stop, the right-main landing gear collapsed.

An investigation found that the forward attachment bolt on the right-main landing-gear drag brace had failed because of fatigue, possibly caused by stress that resulted from “out-of-round bushings in the drag brace,” the final accident report said.

The airplane, which was manufactured in 1973, had been damaged in an off-field emergency landing nine years before this incident. There was no indication that the drag brace or the attachment bolt were replaced during subsequent repairs, and “stress initiators might have been created during the accident that then led to the bolt eventually failing,” the report said.

The accident investigation led to a recommendation that the director of civil aviation publish guidelines for “the appropriate re-use and inspection of parts from accident-damaged aircraft.” The director accepted the recommendation.

Crew Fails to Extend Landing Gear

Cessna Citation 550. Substantial damage. No injuries.

The flight crew was conducting a nighttime emergency medical services flight in Canada with two advanced-life-support paramedics aboard. The first officer, who was type-rated in the airplane, was the pilot flying and was in the left seat, which was consistent with company policy.

At about 10,000 feet during the descent, the crew selected the speed brakes. The accident report said

that the speed brakes remained extended for the remainder of the flight. The airplane flight manual calls for the speed brakes to be retracted no lower than 50 feet.

The crew conducted a nonprecision instrument approach to Runway 30. Surface winds were from 220 degrees at 30 knots, gusting to 37 knots. Because of the wind conditions, the crew decided to land the airplane with the flaps in the approach position, rather than in the landing position.

“The landing-gear-warning horn sounded four times before the aircraft passed the final approach fix (FAF) and was silenced by the crew each time,” the report said. “The first officer did not call for the landing gear to be extended, nor did he call for the ‘Before Landing’ checklist to be completed. The captain did not remind the first officer to extend the landing gear and accomplish the before-landing checks. ... After passing the FAF, the landing-gear-warning horn sounded three more times but was again silenced by the crew.”

The airplane’s nose pitched down just before touchdown on the runway. The flight crew perceived that the landing gear collapsed after touchdown. The airplane slid on its lower fuselage and stopped about 500 feet (153 meters) from the end of the 5,120-foot (1,562-meter) runway.

“The crew carried out an evacuation and proceeded to the airport terminal building,” the report said. “When they returned to the aircraft to retrieve their belongings, the crew discovered that the gear was in the ‘up’ position, as was the landing-gear selector.”

minutes later, radar contact and radio contact were lost. Witnesses said that the night was clear and dark, with no moon. One witness observed an airplane at about 3,000 feet shortly before hearing an explosion.

The wreckage was found at the 3,750-foot level of a mountain.

A friend of the pilot said that in the days before the accident, the pilot had conducted a number of flights to transport his customers around the area and that he had been suffering from a cold.

A preliminary investigation found that the spark plugs in the right engine were worn and that the spark plugs in the left engine were “a combination of ‘worn out — severe’ and ‘worn out — normal.’” The investigation was continuing.

Commander Stalls During Low-altitude Maneuvering

Rockwell 690A Commander. Destroyed. One fatality.

The pilot was flying the twin-turboprop airplane to an airport in the United States to pick up one of its owners. The destination airport was reporting a few clouds at 300 feet, a broken ceiling at 900 feet, an overcast at 3,200 feet, 0.5 statute mile (0.8 kilometer) visibility with snow and surface winds from 290 degrees at 10 knots, gusting to 15 knots.

The pilot conducted a very-high-frequency omnidirectional radio (VOR) approach to Runway 21. Two witnesses said that they heard the pilot report crossing the final approach fix inbound; they observed the airplane emerge from the overcast slightly high and fast, and enter a steeply banked turn. A heavy snowfall then obscured the airplane from their view.

Another witness observed the airplane turn about 270 degrees “just above the power lines.” The witness said that the wings began to wobble, and the airplane pitched nose-down and descended almost vertically to the ground.

The accident report said that the probable causes of the accident were “the pilot’s inadequate [planning for] the approach and his failure to

CORPORATE/BUSINESS

Airplane Strikes Mountain During ‘Dark Night’ Flight

Cessna 310K. Destroyed. One fatality.

Night visual meteorological conditions prevailed for the business flight in the United States, and no flight plan had been filed.

About three minutes after departure, the pilot was told by air traffic control (ATC) that his altitude was “at his discretion, and he said that he was beginning a climb from 3,000 feet. Three



maintain airspeed, which resulted in a stall.” The report said that contributing factors were “low-altitude flight maneuvering in an attempt to lose excessive altitude and realign the airplane for landing, and [the pilot’s] failure to perform a missed approach.”

pilot flew the airplane about five hours without incident.

About one month after the magneto was repaired, the pilot was conducting a takeoff from his private airstrip when engine speed began to decrease and the engine began to run rough. Application of carburetor heat restored normal engine power, and the pilot flew the airplane to an airport where repairs could be made.

After extensive checks and repairs — including adjustment of the fuel-air mixture, cleaning the carburetor and spark plugs and replacement of the induction pipe gaskets — maintenance technicians told the pilot that the engine malfunction had been traced to a “mag problem” and that the problem had been rectified.

The pilot flew the airplane back to his airstrip without incident. On the next flight, the pilot had difficulty hand-starting the engine (by pulling the propeller). Preflight checks of the engine were satisfactory, and the pilot conducted a takeoff. About 150 feet above the ground, the engine failed. The pilot turned right to avoid tall trees and began a descent toward an adjacent valley. At about 50 feet, he increased pitch attitude to reduce the descent rate. The airplane stalled and touched down hard.

The airplane was classified as a total loss by the pilot’s insurance company. “As it will not be repaired, the cause of the engine failure is unlikely to be determined in the near future,” the accident report said.

Airplane Rolls Into Ditch After Hand-starting Procedure

Aeronca 7AC. Substantial damage. No injuries.

The pilot was taxiing the airplane to the runway for takeoff from an airport in Canada when the engine failed. The pilot, who was the only person in the airplane, exited and tried to hand-start the engine.

A preliminary report said that the engine started, and the pilot tried unsuccessfully to stop the airplane as it moved forward, struck a taxiway light, entered a ditch and struck a directional sign.

OTHER GENERAL AVIATION

Broken Pitch-change Knob Cited in Airplane’s Descent Into Water

Socata TB-10 Tobago. Destroyed. Four fatalities.

Daytime visual meteorological conditions prevailed for the sightseeing flight in Denmark. The airplane was in cruise flight between 1,000 feet and 1,500 feet when it descended and struck water just off the coastline.

A preliminary investigation found that one of the propeller blades had failed before the airplane struck the water and had turned approximately 180 degrees, and that engine power probably had been set at “idle” before the accident, the report said. Further investigation revealed that a pitch-change knob had broken on one of the propeller blades.

“If the pitch-change knob breaks off, it will not be possible to control the propeller blade angle, and severe vibrations will occur,” the report said.

The propeller manufacturer had issued a service letter before the accident calling for modification of the pitch-change knob “at the next coming overhaul,” the report said. The accident airplane would have undergone the modification in 2006.

The investigation was continuing.

Engine Fails at 150 Feet During Initial Climb

Luscombe 8A. Destroyed. No injuries.

Four months after the pilot purchased the airplane, he observed a larger-than-normal decrease in engine speed when he turned off the left magneto while preparing for a flight in England. After the left magneto was repaired, the



The airplane did not have a parking brake, and the pilot did not chock the wheels before he started the engine.

Landing Gear Damaged During Go-around

Piper PA-32-301 Saratoga. Substantial damage. No injuries.

The pilot, who had an airline transport pilot certificate, was conducting an approach in daytime visual meteorological conditions to Runway 36 at an airport in the United States. The runway was 2,155 feet (657 meters) long and 70 feet (21 meters) wide, and had a 518-foot (158-meter) displaced threshold.

A nearby airport was reporting surface winds from 200 degrees at nine knots.

The pilot said that after the fixed-gear airplane touched down on the runway, he decided that a go-around was required. He retracted the flaps and applied full power. The left-main landing gear separated from the airplane and the right-main landing gear was bent when they struck an elevated roadway off the end of the runway.

The airplane remained airborne, and the pilot landed it at the nearby airport.

system, an alternative to the conventional anti-torque rotor, uses a fan mounted within the helicopter to produce anti-torque thrust at the tail boom.) All three tests showed that the fan was unbalanced. An inspection of the fan revealed damage to nine of the 13 fan blades and the fan liner but did not determine the cause of the damage.

The fan was replaced, and the damaged blades were sent to the helicopter manufacturer for additional tests. The investigation was continuing.

Sightseeing Helicopter Strikes Power Lines, Tree

Bell 206L-4 LongRanger. Destroyed. Five fatalities, one serious injury.

The helicopter was the second of two aircraft being flown on a charter sightseeing flight in India. About five minutes after departure, the pilot turned the helicopter left, and the helicopter struck a tree.

The accident report said that the probable cause was that the pilot observed power lines “very late” and that he “applied rapid cyclic control, resulting in the helicopter decelerating, loss of translational lift [and] increased power demand, which was not available.”

Helicopter Encounters Downdraft, Strikes Ground

Robinson R22 Beta. Substantial damage. No injuries.

Winds were from the northeast at 15 knots when the pilot conducted a takeoff from a helipad near a mountaintop communications facility in South Africa.

The pilot said that he conducted an in-ground-effect hover check before the liftoff and that he was flying the helicopter about two feet above ground level when the helicopter entered a downdraft and struck the ground about 100 meters (328 feet) from the helipad. ■

ROTORCRAFT

Damaged NOTAR Fan Blades Prompt Precautionary Landing

MD Helicopters MD 902 Explorer. Minor damage. No injuries.

The helicopter was in cruise flight in England when a passenger heard a noise “similar to a seat being moved” that originated above and behind the seating area, the report said. Ten minutes later, the “Check NOTAR Balance” warning illuminated on the integrated instrument display system (IIDS), and the pilot conducted a precautionary landing.

After landing, three tests were conducted on the anti-torque NOTAR fan balance. (The NOTAR



Now you have the safety tools to make a difference.



Flight Safety Foundation

ALAR

Approach-and-landing Accident Reduction

Tool Kit

The Flight Safety Foundation **ALAR Tool Kit** is a comprehensive and practical resource on compact disc to help you prevent the leading causes of fatalities in commercial aviation: approach-and-landing accidents (ALAs), including those involving controlled flight into terrain (CFIT).

Put the FSF ALAR Tool Kit to work for you TODAY!

- Separate lifesaving facts from fiction among the data that confirm ALAs and CFIT are the leading killers in aviation. Use FSF data-driven studies to reveal eye-opening facts that are the nuts and bolts of the FSF *ALAR Tool Kit*.
- Volunteer specialists on FSF task forces from the international aviation industry studied the facts and developed data-based conclusions and recommendations to help pilots, air traffic controllers and others prevent ALAs and CFIT. You can apply the results of this work — NOW!
- Review an industrywide consensus of best practices included in 34 FSF *ALAR Briefing Notes*. They provide practical information that every pilot should know ... *but the FSF data confirm that many pilots didn't know — or ignored — this information*. Use these benchmarks to build new standard operating procedures and to improve current ones.
- Related reading provides a library of more than 2,600 pages of factual information: sometimes chilling, but always useful. A versatile search engine will help you explore these pages and the other components of the FSF *ALAR Tool Kit*. (This collection of FSF publications would cost more than US\$3,300 if purchased individually!)
- Print in six different languages the widely acclaimed FSF *CFIT Checklist*, which has been adapted by users for everything from checking routes to evaluating airports. This proven tool will enhance CFIT awareness in any flight department.
- Five ready-to-use slide presentations — with speakers' notes — can help spread the safety message to a group, and enhance self-development. They cover ATC communication, flight operations, CFIT prevention, ALA data and ATC/aircraft equipment. Customize them with your own notes.
- *An approach and landing accident: It could happen to you!* This 19-minute video can help enhance safety for every pilot — from student to professional — in the approach-and-landing environment.
- *CFIT Awareness and Prevention*: This 33-minute video includes a sobering description of ALAs/CFIT. And listening to the crews' words and watching the accidents unfold with graphic depictions will imprint an unforgettable lesson for every pilot and every air traffic controller who sees this video.
- Many more tools — including posters, the FSF *Approach-and-landing Risk Awareness Tool* and the FSF *Approach-and-landing Risk Reduction Guide* — are among the more than 590 megabytes of information in the FSF *ALAR Tool Kit*. An easy-to-navigate menu and bookmarks make the FSF *ALAR Tool Kit* user-friendly. Applications to view the slide presentations, videos and publications are included on the CD, which is designed to operate with Microsoft Windows or Apple Macintosh operating systems.

Order the FSF ALAR Tool Kit:

Member price: US\$40
Nonmember price: \$160
Quantity discounts available!

Contact: Ahlam Wahdan,
membership services coordinator,
+1 (703) 739-6700, ext. 102.

Recommended System Requirements:

Windows®

- A Pentium®-based PC or compatible computer
- At least 128MB of RAM
- Windows 98/ME/2000/XP system software

Mac® OS

- A 400 MHz PowerPC G3 or faster Macintosh computer
- At least 128MB of RAM
- Mac OS 8.6/9, Mac OS X v10.2.6–v10.3x

Mac OS and Macintosh are trademarks of Apple Computer Inc. registered in the United States and other countries. Microsoft and Windows are either registered trademarks or trademarks of Microsoft Corp. in the United States and/or other countries.

The FSF *ALAR Tool Kit* is not endorsed or sponsored by Apple Computer Inc. or Microsoft Corp.

What can you do to improve aviation safety?

Join Flight Safety Foundation.

Your organization on the FSF membership list and Internet site presents your commitment to safety to the world.

- Receive 54 FSF periodicals including *Accident Prevention*, *Cabin Crew Safety* and *Flight Safety Digest* that members may reproduce and use in their own publications.
- Receive discounts to attend well-established safety seminars for airline and corporate aviation managers.
- Receive member-only mailings of special reports on important safety issues such as controlled flight into terrain (CFIT), approach-and-landing accidents, human factors, and fatigue countermeasures.
- Receive discounts on Safety Services including operational safety audits.



Flight Safety Foundation

An independent, industry-supported, nonprofit organization for the exchange of safety information for more than 50 years



Want more information about Flight Safety Foundation?

Contact Ann Hill, director, membership and development
by e-mail: <ahill@flightsafety.org> or by telephone: +1 (703) 739-6700, ext. 105.

Visit our Internet site at <www.flightsafety.org>.

We Encourage Reprints

Articles in this publication, in the interest of aviation safety, may be reprinted in whole or in part, but may not be offered for sale directly or indirectly, used commercially or distributed electronically on the Internet or on any other electronic media without the express written permission of Flight Safety Foundation's director of publications. All uses must credit Flight Safety Foundation, *Flight Safety Digest*, the specific article(s) and the author(s). Please send two copies of the reprinted material to the director of publications. These restrictions apply to all Flight Safety Foundation publications. Reprints must be ordered from the Foundation. For more information, contact the director of publications by telephone: +1 (703) 739-6700, ext. 116; or by e-mail: <rozelle@flightsafety.org>.

What's Your Input?

In keeping with the Foundation's independent and nonpartisan mission to disseminate objective safety information, FSF publications solicit credible contributions that foster thought-provoking discussion of aviation safety issues. If you have an article proposal, a completed manuscript or a technical paper that may be appropriate for *Flight Safety Digest*, please contact the director of publications. Reasonable care will be taken in handling a manuscript, but Flight Safety Foundation assumes no responsibility for material submitted. The publications staff reserves the right to edit all published submissions. The Foundation buys all rights to manuscripts and payment is made to authors upon publication. Contact the Publications Department for more information.

Flight Safety Digest

Copyright © 2004 by Flight Safety Foundation Inc. All rights reserved. ISSN 1057-5588

Suggestions and opinions expressed in FSF publications belong to the author(s) and are not necessarily endorsed by Flight Safety Foundation. This information is not intended to supersede operators'/manufacturers' policies, practices or requirements, or to supersede government regulations.

Staff: Roger Rozelle, director of publications; Mark Lacagnina, senior editor; Wayne Rosenkrans, senior editor; Linda Werfelman, senior editor; Rick Darby, associate editor; Karen K. Ehrlich, web and print production coordinator; Ann L. Mullikin, production designer; Susan D. Reed, production specialist; and Patricia Setze, librarian, Jerry Lederer Aviation Safety Library

Subscriptions: One year subscription for 12 issues includes postage and handling: US\$480. Include old and new addresses when requesting address change. • Attention: Ahlam Wahdan, membership services coordinator, Flight Safety Foundation, Suite 300, 601 Madison Street, Alexandria, VA 22314 U.S. • Telephone: +1 (703) 739-6700 • Fax: +1 (703) 739-6708 • E-mail: <wahdan@flightsafety.org>